




TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 May 2022, 11:56:31
Transaction Number	55570033 (CC10008)	Queue Number	312309



Chassis Number	RKLBV42E2C4431787
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Corolla
Model Year	2012
Color	Beige
Mileage	663416 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
01.C Gear Box Mount	BUSH CRACKED	كرسي الجير
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2017/2019 CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
03 Interior Condition		الحاله الداخليه
03.A Power Window Switch	FRONT RIGHT SIDE NOT WORKING	مفتاح النافذه
03.B AC Condition	OK	المكيف
03.C Dash Board	WORN OUT	لوحة القيادة
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK	حالة المحرك النظري
04.B Mount	MOUNT BUSH CRACKED	كرسي
05 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
05.A Arms	LOWER ARM BUSHES CRACKED	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
05.C Shock Absorber	REAR RIGHT SIDE OIL LEAK & FRONT BOTH SIDE UPPER MOUNT BUSHES CUT	ممتص الصدمات
06 Chassis Condition		الشاسي
06.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION REPAIRED, STILL BEND	الشاسيه
07 Body		جسم المركبة
07.A Other	REAR BACK PANEL, QUATER PANEL REPAIRED	اخرى
07.B Trunk	REFITTED	صندوق
07.C Sign of front accident		وجود مؤشر لحادث في المقدمة
07.D Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
07.E Sign of back accident		وجود مؤشر لحادث في الخلف
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CRACK	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate

✓ PASS



Vehicle
Registration



RTA

Transfer Certificate :	65189272
Chassis No :	RKLBV42E2C4431787
Vehicle Make :	TOYOTA
Vehicle Model :	COROLLA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Piege
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	663412 Kms.
Origin :	Taiwan
Model Year :	2012
Gear Type :	Automatic
Engine No :	1zr0837792
Engine Size :	1800 CC
Axles No :	2
No Of Doors :	4
G. V. W. :	1600 Kgs.
Model Year :	2012
Engine Size :	1800 CC
Horse Power :	64
Cylinders :	4
No Of Seats :	5
Empty Weight :	1200 Kgs.

Certificate Number :	5-TAS-2022-16842227
Inspection Date :	25-05-2022
Certificate Print Date :	25-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 35 sec
Appointment Ref Number :	--
Start Time :	10:43
End Time :	10:52
Lane :	02
Token No. :	129
Attempt :	1
Prints No. :	4

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)

104724 KM	7441 L	12055 AED	17.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	3 %	3 %	0 %
Vehicle on Petrol HC Reading			
2 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1800	1600	

Inspection Remarks:

Rear left side chassis, back panel, front bulk head, radiator frame, fender frame repaired front left side chassis repaired OLD/MINOR ENGINE OIL LEAK

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460 34439	Cash	16842227	AED 170 Collected on 25/05/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة مالة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

