







Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 27732160 Plate Category : PRIVATE

Transaction Date : 10 JUL 2021 15:05:21 Plate Number : 788024 EA

Queue Number : 365188

Chassis Number : JMYSRCS1A5U788024 Manufacturer/Model : MITSUBISHI/LANCER

Engine Number :

Import Doc. Ref.

Vehicle Class : LIGHT VEHICLE
Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

		•	Statement of Vehicle Condition
Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			لفر امل
13.04 - Brake Test	Passed		لحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
16 Side Slip Test			فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed		فحص ميز انية الإطارات
VISUAL TEST:			
01 Lights			الانوار
01.02 - Tail Lights		BOTH SIDE CRACK	ألانوار الخلفية
02 Steering And Suspension System			عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		FRONT LEFT SIDE OUTER AXLE BOOT CRACK & AXLE NOISY	المحور
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		TIRES 2018 &REAR LEFT SIDE PUNCTUR /TEST DRIVE NOT DONE	الإطارات الإمامية RE
05 Body			الهيكل
05.01 - Rusty		UNDER BODY COMPONENTS PARTLY RUSTY	الصدأ
05.02 - Paint		BODY SCRATCH & DENT	الصبغ
05.04 - Fenders		REAR BOTH SIDE QUARTER PANEL REPAIRED	المدكار
05.07 - Floor		REAR FLOOR PAN/BACK PANEL REPAIRED & MIDDLE FLOORING & REINFORCEMENT DENT	الارضية
05.08 - Chassis (Frame)		REAR RIGHT SIDE FRAME MEMBER END REPAIRED	الشاصية
05.12 - Side Safety Frame		BULKHEAD/RADIATOR SUPPORT & FRONT BUMPER SUPPORT FRAME REPAIRED	لواقيات الجانبية
06 General Items			الاشياء العامة
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORN OUT & DIRTY	لمقاعد وحالتها وتثبيتها
06.21 - Battery Condition		BATTERY UNSECRE/BRACKET NOT FIX	حالة البطارية
07 Remarks			ملاحظات





Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 27732160 Plate Category : PRIVATE

Transaction Date : 10 JUL 2021 15:05:21 Plate Number : 788024 EA

Queue Number : 365188

Chassis Number : JMYSRCS1A5U788024 Manufacturer/Model : MITSUBISHI/LANCER

Engine Number :

Vehicle Class : LIGHT VEHICLE Vehicle Color : WHITE

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

2005

Import Doc. Ref.

Model Year

09 Auction لكامل lbald الكامل

ش حادث في مؤخرة المركبة BACK PANEL REPAIRED

50.10 Sign of real resident

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

09.18 - A/C Not Cooling

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط

تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Transfer Certificate: 65328698 JMYSRCS1A5U788024 Chassis No: Vehicle Make: MITSUBISHI Vehicle Model: LANCER Vehicle Class: Light Vehicle **Body Type:** SALOON Fuel: Benzene Color: White **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 743313 Kms. Origin: Japan Model Year: 2005 1300 CC Gear Type: **Engine Size:** Engine No: 4G13GH9284 **Horse Power:** Axles No: Cylinders: No Of Doors: 4 No Of Seats: G. V. W.: Empty Weight: 1200 Kgs. 1800 Kas.

Certificate Number :	5-TAS-2021-14619434		
Inspection Date :	14-07-2021		
Certificate Print Date :	14-07-2021		
Services :	Registration Test		
Vehicle Testing Partner:	Tasjeel		
Vehicle Testing Center:	Tasjeel Emirates Auction		
Total Time Taken:			
6 min 57 sec			
Appointment Ref Number :			
Start Time: 11:02	End Time: 11:09		
Lane: 01	Token No.: 8		
Attempt: 1	Prints No: 1		

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)



534 KM

Distance per

year

30 L Fuel consumed per year



0.1ton Fuel cost per Carbon footprint vear per year

Parameter Readings

Service brake imbalance on front axle

13 %

Service brake imbalance on rear axle 5%

Parking brake imbalance between LHS and RHS

Vehicle on Petrol CO Reading 0.28 %

Reading 134 PPM VOL

Vehicle on Petrol HC

Inspection Remarks:

FRONT & REAR BUMPER & FRAME REPAIRED / REAR COMPARTMENT BACK PANEL & FLOOR REPAIRED / REAR BOTH SIDE WHEEL HOUSING RUSTED & REPAIRED/ LEFT SIDE AXLE BOOT CRACK / REAR RIGHT SIDE FRAME MEMBER END REPAIRED

Payment Details

Inspection Performed by **Payment Method Transaction Number Service Fees** 59460 VTP Credit Account 14619434 AED 170 Collected on 14/07/2021 Received by **Parking Slot No Attempt** Service Name **Registration Test** Raul Canceran Galang

- 10 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. 👖 هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

لقانون السير و المرور أ2 لسنة 1995 This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995