



## TEST CERTIFICATE

|                    |                       |                  |                       |
|--------------------|-----------------------|------------------|-----------------------|
| Site Number        | 840-Emirates Auctions | Transaction Date | 27 Nov 2022, 15:20:59 |
| Transaction Number | 60807612 (CC10009)    | Queue Number     | 631127                |



|                  |                   |
|------------------|-------------------|
| Chassis Number   | WDB2304751F040109 |
| Engine Number    |                   |
| Vehicle Class    | Car               |
| Manufacturer     | Mercedes          |
| Model            | SL 500            |
| Model Year       | 2005              |
| Color            | Silver            |
| Mileage          | 98833 Km          |
| Fuel Type        | Petrol            |
| No. Of Cylinders | 8                 |
| Specification    | Imported          |

| DEFECT                                  | REMARKS  |                            |
|---|--|----------------------------|
| <b>01 Steering Condition</b>            |  |                            |
|   |  | المقود                     |
| 01.A Tie Rod End                        | BOOT CUT   | مؤخرة الرودادات            |
| 01.B Steering Oil                       | LEAK   | زيت المقود                 |
| <b>02 Interior Condition</b>            |  |                            |
|   |  | الحاله الداخليه            |
| 02.A Other                              | GEAR LEVER SIDE COVER DAMAGED                              | اخرى                       |
| 02.B AC Condition                       | NOT WORKING  | المكيف                     |
| 02.C Steering Wheel and control buttons | WORN OUT,  | عجلة القيادة وازرار التحكم |
| 02.D Audio                              | FADED  | صوتيات                     |
| 02.E Door Panel                         | PORTION LOOSE/ LEFT SIDE LOCK LEVER DAMAGED                | لوحة بطانة الباب           |
| 02.F Dash Board                         | PORTION LOOSE  | لوحة القيادة               |
| 02.G Mirror                             | LEFT SIDE LOOSE  | المرايا                    |
| <b>03 Body</b>                          |  |                            |
|   |  | جسم المركبة                |
| 03.A Sign of front accident             |  | وجود مؤشر لحادث في المقدمة |
| 03.B Roof                               | ROOF CONVERTABLE NOT WORKING                               | السقف                      |
| 03.C Paint                              | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES, | الصبغ                      |

| DEFECT                             | REMARKS  |                     |
|------------------------------------|--|---------------------|
| 03.D Floor                         | UNDER FLOOR FENDER CHASSIS FRAME FULLY COVERED<br>CHECKED VISIBLE AREA | الارضية             |
| <b>04 Engine Condition</b>         |  | <b>المحرك</b>       |
| 04.A Other                         | ENGINE START SWTICH PANEL LOOSE KEY NOT<br>CONNECTING PROPERLY         | اخرى                |
| 04.B Visual Engine Condition       | OVER HEAT , OIL LEAK REFITTED ABNORMAL NOISY                           | حالة المحرك النظرى  |
| <b>05 Suspension System</b>        |  | <b>ممتص الصدمات</b> |
| 05.A Ball Joint                    | BOOT CUT   | مفصل كروي           |
| 05.B Arms                          | LOWER ARM BUSH CRACKED   | ازرع                |
| <b>06 Lights</b>                   |  | <b>الاضاءة</b>      |
| 06.A Head Light                    | LENS FADED   | الاضاءة الرئيسية    |
| 06.B Other                         | SWTICH PANEL DAMAGED   | اخرى                |
| <b>07 Transmission Condition</b>   |  | <b>الجير</b>        |
| 07.A Visual Gear Box<br>Condition  | OIL LEAK REFITTED JERKING  | حالة الجير النظرى   |
| 07.B Gear Box Mount                | MOUNT RUBBER CRACKED   | كرسي الجير          |
| 07.C Road Test                     | NOT CHECK,   | فحص علي الطريق      |
| <b>08 Tires and Rims Condition</b> |  | <b>الاطارات</b>     |
| 08.A Front Tyre                    | BOTH SIDE 2019 CRACKED ,   | الاطار الامامي      |
| 08.B Rear Tyre                     | BOTH SIDE 2020 CRACKED   | الاطار الخلفي       |
| <b>09 Seats Condition</b>          |  | <b>المقاعد</b>      |
| 09.A Other                         | RIGHT SIDE ADJUSMENT NOT WORKING                                       | اخرى                |
| <b>10 Chassis Condition</b>        |  | <b>الشاسي</b>       |
| 10.A Chassis                       | CHASSIS COVERED CHECKED VISIBLE AREA ONLY /OK                          | الشاسيه             |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.