



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Sep 2021, 11:31:06
Transaction Number	12658530 (CC10006)	Queue Number	312309



Chassis Number	1GCEC14X74Z226712
Engine Number	
Vehicle Class	Heavy
Manufacturer	Chevrolet
Model	Silverado
Model Year	2004
Color	Red
Mileage	10082

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	BOTH SIDE REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	BOTH SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, FLOORING , CHASSIS FRAME GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY RUST PROOFED & REAR BOX FIBER	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.I Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED OLD GETTING RUSTY	اخرى
01.J Windshield	FRONT HAVE SPOT CRACK	زجاج
02 Chassis Condition		الشاسي
02.A Chassis Extension	REAR BOTH SIDE END REPAIRED & DENT	تمديدات الشاسي
02.B Chassis	CHASSIS FRAME COMPLETELY THICK RUST PROOFED	الشاسيه
02.C Other	FOR RECHECK PROPERLY NEED TO ROMOVE RUST PROOFED	اخرى
03 Engine Condition		المحرك

DEFECT	REMARKS	
03.A Other	OK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
08 Steering Condition		المقود
08.A Steering Boot	BOOT LEAKING	ربلة المقود
08.B Other	STABILIZER LINK & CONTROL BAR BUSHES DRY CRACKED	اخرى
08.C Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
09 Interior Condition		الاجزاء الداخلية
09.A Other	OK	اخرى
09.B Mirror	OK	المرآيا
09.C AC Condition	OK	المكيف
10 Suspension System		ممتص الصدمات
10.A Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	1GCEC14X74Z226712
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Red
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	10084 Kms.
Origin :	United States
Model Year :	2004
Gear Type :	--
Engine Size :	6000 CC
Engine No :	NIL
Horse Power :	195
Axles No :	2
Cylinders :	6
No Of Doors :	2
No Of Seats :	3
G. V. W. :	Empty Weight : 2125 Kgs. 3130 Kgs.

Certificate Number :	5-TAS-2021-15041601
Inspection Date :	18-09-2021
Certificate Print Date :	18-09-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	26 min 59 sec
Appointment Ref Number :	--
Start Time :	16:03
End Time :	16:29
Lane :	02
Token No. :	203
Attempt :	1
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

504 KM	52 L	85 AED	0.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 12 %	Service brake imbalance on rear axle 11 %	Parking brake imbalance between LHS and RHS 7 %	Vehicle on Petrol CO Reading 0.1 %
Vehicle on Petrol HC Reading 46 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Cylinders Incorrect number of cylinders	6	8	

Inspection Remarks:

front left fender,fender frame , bulk head repaired // engine and gear oil minor leak// rear chassis end repaired // front windshield minor spot crack.

Payment Details

Inspection Performed by 33706	Payment Method VTP Credit Account	Transaction Number 15041601	Service Fees AED 170 Collected on 18/09/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

