



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>07 Jan 2022, 12:03:59</b>
Transaction Number	<b>34418020 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDD2211561A024679</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>S 350</b>
Model Year	<b>2006</b>
Color	<b>Black</b>
Mileage	<b>90356 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	RIGHT SIDE BOTH REPAINTED & REAR LEFT SIDE PORTION REPAIRED, REPAINTED	مدكار
01.B Bonnet	PORTION REPAIRED , REPAINTED & GRAIL PORTION DAMAGED, LOGO MISSING	غطاء المحرك
01.C Doors	LEFT SIDE BOTH , REAR RIGHT SIDE REPAINTED & FRONT RIGHT SIDE PORTION REPAIRED, REPAINTED	أبواب
01.D Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.E Floor	UNDER BODY COVERD	الارضية
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Dash Board	DASH BOARD PORTION DAMAGED & CENTER CONSOLE BOX,CUP BOX COVER DAMAGED	لوحة القيادة
02.B Sun Visor	BOTH SIDE MIRROR COVER PORTION DAMAGED, LOOSE & RIGHT SIDE MIRROR CRACKED	حاجب الشمس
02.C Door Panel	FRONT LEFT SIDE HANDLE LOOSE & REAR SIGRATE BOX COVER DAMAGED	لوحة بطانة الباب
02.D Mirror	CENTER MIRROR STAND COVER MISSING & RIGHT SIDE COVER PORTION CRACKED	المرابا
02.E Roof Ceiling	REAR PORTION LOOSE	بطانه السقف

DEFECT	REMARKS	
02.F Sunroof	CURTAIN NOT WORKING	فتحت سقف
02.G AC Condition	OK	المكيف
<b>03 Seats Condition</b>		<b>المقاعد</b>
03.A Seat Condition	FRONT BOTH SIDE ADJUSTMENT BUTTON MISSING & REAR SEAT COVER PORTION CRACKED	حالة المقاعد
03.B Other	FRONT RIGHT SIDE BACK COVER LOOSE	اخرى
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Head Light	OK	الاضاءة الرئيسية
04.B Brake Light	LEFT SIDE COVER CRACKED	نور الفرامل
<b>05 Wipers and Arms</b>		<b>المساحات</b>
05.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>06 Chassis Condition</b>		<b>الشاصي</b>
06.A Chassis	VISABLE AREA OK	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Engine Condition	OIL LEAK	حالة المحرك
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OIL LEAK	الجير
08.C Propeller Shaft	RUBBER CUT	ناقل الحركة
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2015 EXPIRED,CRACKED	الاطار الخلفي
09.C Rims Condition	SCRATCHES	حالة الجنوط

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.