

Queue Number 2877846

Transaction Date 19 Oct 2026, 13:41:51

Site Name
840 - Emirates AuctionsTransaction Number
62950544 (CC10010) (CC10010)

Vehicle Details

Chassis Number SALFA24A27*****
 Specification GCC Specification
 Make Land Rover
 Model LR2-HSE
 Model Year 2007
 Color Black
 Mileage N/A Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY , CHECKED ONLY VISIBLE AREA PORTION DENT .	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,COOLANT MIXED	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	CRACKED WORN OUT	الاطار الامامي
05.B Rear Tyre	CRACKED WORN OUT DAMAGED.	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك و طنايبر الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
09.C Axle	BOOT CUT .	اكسلات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS RUSTY,SIGN WATER FLOODED.	اخرى
10.B Mirror	LOOSE FADED.	المرايا
10.C Floor Matting	CENTER CONSOLE DAMAGED.	فرش الأرضية
10.D Dash Board	DIRTY LOOSE PORTION DAMAGED	لوحة القيادة
10.E Roof Ceiling	LOOSE	بطانة السقف
10.F Sun Visor	LOOSE	حاجب الشمس
10.G Odometer reading	NOT CHECKED.	قراءة عداد المسافات
10.H Door Panel	WORN OUT PORTION DAMAGED	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.J Sunroof	CURTAIN DAMAGED . OPEN	فتحت سقف
10.K Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae