



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Aug 2022, 13:27:18
Transaction Number	19918393 (CC10006)	Queue Number	312309



Chassis Number	2G1F93DJ7B9158275
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Camaro
Model Year	2011
Color	Orange
Mileage	174254 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAINTED REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.B Bumper	MISALIGN	دعامية
01.C Bonnet	REFITTED	غطاء المحرك
01.D Sign of side accident		وجود مؤشر لحادث في الجانب
01.E Floor	RIGHT SIDE MIDLE FLOOR DAMAGED	الارضية
01.F Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.G Sign of front accident		وجود مؤشر لحادث في المقدمة
01.H Fenders	REAR LEFT SIDE INNER QUARTER PANEL REPAIRED.	مدكار
01.I Trunk	REFITTED.	صندوق
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	REFITTED & MINOR OIL LEAK	حالة الجير النظرى
03 Interior Condition		الحالة الداخليه
03.A Sunroof	NOT WORKING	فتحت سقف

DEFECT	REMARKS	
03.B AC Condition	OK	المكيف
04 Steering Condition		المقود
04.A Steering Oil	LEAK	زيت المقود
04.B Tie Rod End	BOOT CRACK	مؤخرة الرودات
05 Lights		الاضاءة
05.A Tail Light	STICKERD.	الانارة
05.B Indicator & Hazard light	REAR RIGHT SIDE NOT WORKING	الاشارات
05.C Head Light	RIGHT SIDE LOW INTENSITY.	الاضاءة الرئيسية
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
07 Engine Condition		المحرك
07.A Visual Engine Condition	REFITTED	حالة المحرك النظري
08 Chassis Condition		الشاسي
08.A Chassis	FRONT RIGHT SIDE CHASSIS DENT & BEND.	الشاسيه
08.B Chassis Number	CHASSIS VIN NUMBER STICKER DOOR POST SIDE MISSING	رقم القاعدة
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CRACK	مفصل كروي
09.B Arms	LOWER ARM BUSHES CRACKED	ازرع
10 Exhaust System		نظام العادم
10.A Modification	MODIFIED	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



✓ PASS

Vehicle
Registration



Transfer Certificate :	62261235
Chassis No :	2G1F93DJ7B9158275
Vehicle Make :	CHEVROLET
Vehicle Model :	CAMARO
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Orange
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	174260 Kms. x
Previous Odometer Reading :	235446 Kms.
Origin : Canada	Model Year : 2011
Gear Type : Automatic	Engine Size : 6000 CC
Engine No : NONE	Horse Power : --
Axles No : 2	Cylinders : 8
No Of Doors : 2	No Of Seats : 4
G. V. W. : 1800 Kgs.	Empty Weight : 1650 Kgs.

Certificate Number :	5-TAS-2022-17400367		
Inspection Date :	14-08-2022		
Certificate Print Date :	14-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	16 min 57 sec		
Appointment Ref Number :	--		
Start Time :	8:33	End Time :	8:50
Lane :	01	Token No. :	104
Attempt : 1		Prints No :	2

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)

61712 KM	6350 L	20701 AED	15.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 6 %	Service brake imbalance on rear axle 2 %	Parking brake imbalance between LHS and RHS 3 %	Vehicle on Petrol CO Reading 0.03 %
Vehicle on Petrol HC Reading 89 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks:

Front bumper,bulk head,front right side frame member outer skirt repaired/dent.rear left quarter panel,wheel arch repaired old km-235446 on 01-03-2022



Odometer Record
Replace Events Date

14/08/2022

Payment Details

Inspection Performed by 35063 3104 3104	Payment Method Cash	Transaction Number 17400367	Service Fees AED 170 Collected on 14/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.



تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أُصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.