




TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 Sep 2022, 15:56:23
Transaction Number	72672768 (CC10009)	Queue Number	596555



Chassis Number	1FAHP2DWXBG132708
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Taurus
Model Year	2011
Color	Black
Mileage	308316 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Bonnet	PORTION REPAIRED,REPAINTED & REFITTED, SHOCK WEAK	غطاء المحرك
01.B Trunk	REPAINTED	صندوق
01.C Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.D Fenders	FRONT BOTH SIDE , REAR LEFT SIDE PORTION REPAIRED & REPAINTED & REAR RIGHT REPAINTED , REFITTED	مدكار
01.E Doors	LEFT SIDE BOTH PORTION REPAIRED, REPAINTED & RIGHT SIDE BOTH REPAINTED	أبواب
01.F Other	FRONT BUMPER FRAME BULK HEAD REPAIRED	اخرى
01.G Floor	FLOOR RUST PROOFED	الارضية
01.H Roof	REAR LEFT SIDE ROOF RAILL PORTION REPAIRED REPAINTED	السقف
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
01.J Sign of front accident		وجود مؤشر لحادث في المقدمة
01.K Pillars	REAR LEFT SIDE QUARTER PANEL REPAIRED REPAINTED	القوائم
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box Mount	MOUNT CRACKED	كرسي الجير

DEFECT	REMARKS	
02.C Visual Gear Box Condition	MINOR OIL LEAK / JERKING	حالة الجير النظري
03 Interior Condition		الحالة الداخليه
03.A Roof Ceiling	REAR LOOSE	بطانه السقف
03.B AC Condition	OK	المكيف
03.C Mirror	RIGHT SIDE GLASS CRACKED	المرابا
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
05 Chassis Condition		الشاصي
05.A Chassis Number	MANUFACTUR STICKER DAMAGED	رقم القاعدة
05.B Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Shock Absorber	REAR BOTH SIDE LEAK	ممتص الصدمات
09 Engine Condition		المحرك
09.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.