



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Jul 2022, 16:11:39
Transaction Number	95592358 (CC10006)	Queue Number	312309



Chassis Number	SALLSAA349A195412
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2009
Color	Black
Mileage	100 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Sunroof	BUTTON MISSING NOT OPEN	فتحت سقف
01.B Roof Ceiling	PORTION LOOSE	بطانه السقف
01.C Dash Board	PORTION LOOSE , HAND REST COVER DAMAGED	لوحة القيادة
01.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.E Other	GEAR LEVER COVER WORN OUT	اخرى
01.F AC Condition	NOT COOLING	المكيف
02 Brake Condition		الفرامل
02.A Brake Pedal	SPONGY WEAK	دواسة الفرامل
03 Engine Condition		المحرك
03.A Smoke	WHITE SMOKE	دخان
03.B Mount	MOUNT RUBBER CRACKED	كرسي
03.C Visual Engine Condition	SHAKING OIL LEAK REFITTED	حالة المحرك النظري
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES	الصبغ
05.B Bonnet	REFITTED	غطاء المحرك
05.C Sign of front accident		وجود مؤشر لحادث في المقدمة
05.D Other	FRONT BUMPER FRAME BULK HEAD REPAIRED	اخرى
05.E Floor	COVER PORTION DAMAGED	الارضية
05.F Fenders	REFITTED	مدكار
06 Seats Condition		المقاعد
06.A Seat Condition	PORTION DAMAGED	حالة المقاعد
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
07.C Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظري
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM CONTROL ARM BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Other	STABILIZER LINK BOOT CUT	اخرى
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10.B Steering Oil	MINOR OIL LEAK	زيت المقود
10.C Axel	BOOT CUT	اكسلات
11 Chassis Condition		الشاسي
11.A Chassis	FRONT RIGHT SIDE SLIGHTLY BEND MOUNT MINOR DENT, CHASSIS FRAME THICK RUSTPROOOFED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	SALLSAA349A195412
Vehicle Make :	RANGE ROVER
Vehicle Model :	RANGE ROVER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	162422 Kms. x
Origin : Great Britain	Model Year : 2009
Gear Type : Automatic	Engine Size : 4200 CC
Engine No : 140708B1122...	Horse 301
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 2650 Kgs.	Empty 2648 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17335079
Inspection Date :	03-08-2022
Certificate Print Date :	03-08-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	7 min 43 sec
Appointment Ref Number :	--
Start Time : 15:44	End Time : 15:52
Lane : 03	Token No. : 207
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	3 %	1 %	1.21 %
Vehicle on Petrol HC Reading			
1754 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major
Dip beams(Low Beams) headlight	Busted bulb	Major
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major
Engine repair white smoke	Excessive oil smoke	Major
Engine repair oil leak	Oil leaking continuously	Major

Inspection Remarks: Front&rear bumper,bulk head,fenders repaired,chassis rust proofed.



Odometer Record
Replace Events Date

20/07/2022

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
35063	Cash	17335079	AED 170 Collected on 03/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.