



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>15 Aug 2022, 10:51:40</b>
Transaction Number	<b>36556948 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1G1JB5SH3J4100224</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Sonic</b>
Model Year	<b>2018</b>
Color	<b>White</b>
Mileage	<b>001 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b> <span style="float: right;">المحرك</span>		
01.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,MINOR OIL LEAK,REFITTED	حالة المحرك النظري
<b>02 Transmission Condition</b> <span style="float: right;">الجير</span>		
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	MINOR OIL LEAK,REFITTED	حالة الجير النظري
<b>03 Interior Condition</b> <span style="float: right;">الحاله الداخليه</span>		
03.A AC Condition	NOT CHECK	المكيف
03.B Odometer reading	NOT CHECK	قراءة عداد المسافات
03.C Air Bag	DAMAGED	وسائد هوائية
03.D Other	INTERIOR DUSTY	اخرى
<b>04 Body</b> <span style="float: right;">جسم المركبة</span>		
04.A Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES	الصبغ
04.B Fenders	FRONT REFITTED	مدكار
04.C Bonnet	REFITTED	غطاء المحرك
04.D Trunk	NOT OPEN	صندوق

DEFECT	REMARKS	
04.E Rusty	UNDER FLOOR GETTING MINOR RUSTY	صدأ
04.F Bumper	MISALIGN	دعامية
04.G Other	FRONT BUMPER FRME BULK HEAD FENDER FRAME FAIRWALL COIL PANEL REPAIRED	اخري
04.H Floor	PORTION REPAIRED MINOR DENT	الارضية
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	BOTH SIDE 2016 CRACKED , EXPIRED	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2016 CRACKED , EXPIRED	الاطار الامامي
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.B Axel	FRONT AXLE BOOT LEAK	اكسلات
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Ball Joint	BOOT CUT	مفصل كروي
08.B Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>09 Chassis Condition</b>		<b>الشاصي</b>
09.A Chassis Number	VIN PUNCHING AREA REPAIRED FOR RECHECK PROPERLY REMOVE COIL PANEL COVERS	رقم القاعدة
09.B Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.