



Test Certificate

Import Doc. Ref.

Model Year

Site Number : 756-TASJEEL SHARJAH Plate Code : 0

Transaction Number : 18674488 Plate Category : PRIVATE

Transaction Date : 05 DEC 2019 11:23:11 Plate Number : 06323AUC

Queue Number : 123366

Chassis Number : MR0ES12G093306323 Manufacturer/Model : TOYOTA/HILUX

Engine Number :

Vehicle Class: LIGHT VEHICLEVehicle Color: WHITEService / Indicator: DSC AUCTIONMileage: 354309

Statement of Vehicle Condition

2009

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفر امل
13.04 - Brake Test	Failed		فحص الفر امل
14 Exhaust Gas Test			- الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
17 Shock Absorbers Test			فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed		فحص مخمد الصدمات
VISUAL TEST:			
03 Brake System			نظام الفرامل
03.06 - Brake Hose And Piping		RR LHS BRAKE FLUID HOSE PIPE LEAKS.	انابيب الفرامل
05 Body			. ي . الهيكل
05.01 - Rusty		BODY PARTS DOOR POSTS PARTLY	الصدأ
05.07 - Floor		RUSTY. UNDER FLOOR PARTLY & BODY MOUNTINGS PURTER HOLER	الارضية
05.08 - Chassis (Frame)		MOUNTINGS RUSTED HOLED. CHASSIS FRAME PARTLY RUSTED HOLED & COMPLETE RUST PROOFED DUE TO RUST.	الشاصية
05.12 - Side Safety Frame		CHASSIS FRAME PARTLY DENTS & BULGED.	الواقيات الجانبية
06 General Items			الأشياء العامة
06.04 - Horn		NOT WORKING.	الزامور
06.12 - Seats Condition And Seats Fixing		SEATS UPHOLSTERY DAMAGED.	المقاعد وحالتها وتثبيتها
06.16 - Engine Condition, Smoke		INJECTOR MINOR LEAKS.	حالة المحرك - الدخان
09 Auction			الفحص الكامل
09.02 - Need Wheel Alignment			بحاجة الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok		OK	فحص حالة الماكينة والجير
09.10 - Engine Oil Leaking			تهريب زيت المحرك
09.25 - Body Repainted		BODY ALL PORTIONS REPAINTED EXCEPT ROOF TOP.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط