



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>16 Nov 2021, 17:44:45</b>
Transaction Number	<b>32459939 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>6G1LM54F36L833176</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Caprice LS</b>
Model Year	<b>2006</b>
Color	<b>White</b>
Mileage	<b>370000 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2017 CRACKED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	FRONT LEFT SIDE CHASSIS BEND &END REPAIRED	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Engine Condition	OIL LEAK,VIBRATION	حالة المحرك
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OK	الجير
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Steering Boot	BOOT CUT	ربلة المقود
05.B Steering Oil	MINOR OIL LEAK	زيت المقود
<b>06 Wipers and Arms</b>		<b>المساحات</b>
06.A Wiper Arm &Blade	WORNOUT	ازرع المساحات والشفرات

DEFECT	REMARKS	
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Door Handle &Lock	FRONT RIGHT SIDE INNER HANDLE BROKEN MISSING &REAR LEFT LOCK MISSING	مقابض الأبواب والأقفال
07.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
07.C Fenders	FRONT BOTH SIDE &REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
07.D Doors	LEFT SIDE BOTH &REAR RIGHT SIDE DOOR REPAINTED,PORTION REPAIRED	أبواب
07.E Bonnet	REPAINTED,PORTION REPAIRED,SHOCK STAND NOT WORKING	غطاء المحرك
<b>08 Interior Condition</b>		<b>الحالة الداخلية</b>
08.A AC Condition	OK	المكيف
08.B Power Window Switch	NOT WORKING EXCEPT DRIVER SIDE	مفتاح النافذة
08.C Other	GEAR BOX CONSOLE BOX CRACKED &SHIFTING LEVER KNOB BUTTON LOOSE	اخرى
08.D Mirror	VIEW MIRROR FADED	المرآيا
08.E Dash Board	DISPLAY SCREEN FADED	لوحة القيادة
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
09.B Fog light	NOT WORKING	كشاف الضباب
09.C Head Light	HIGH BEAM NOT WORKING	الاضاءة الرئيسية
09.D Tail Light	REAR RIGHT SIDE BROKEN	الانارة
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Condition	DRIVER SEAT DAMAGED&BACK COVER LOOSE	حالة المقاعد
10.B Seat Belt	OK	حزام الأمان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Change possession :	65369154
Chassis No :	6G1LM54F36L833176
Vehicle Make :	CHEVROLET
Vehicle Model :	CAPRICE LS
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	408265 Kms.
Origin :	Australia
Model Year :	2006
Gear Type :	--
Engine Size :	5000 CC
Engine No :	NIL
Horse Power :	213
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	2000 Kgs.
Empty Weight :	1000 Kgs.

Certificate Number :	5-TAS-2021-15496546
Inspection Date :	20-11-2021
Certificate Print Date :	20-11-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	15 min 37 sec
Appointment Ref Number :	--
Start Time :	17:15
End Time :	17:30
Lane :	01
Token No. :	206
Attempt :	1
Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate in 12 Months)



22681 KM

Distance per  
year



2334 L

Fuel consumed  
per year



3782 AED

Fuel cost per  
year



5.6 ton

Carbon footprint  
per year

## Parameter Readings

Service brake imbalance on  
front axle  
6 %

Service brake imbalance on  
rear axle  
11 %

Parking brake imbalance  
between LHS and RHS  
9 %

Vehicle on Petrol CO  
Reading  
0 %

Vehicle on Petrol HC  
Reading  
2 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5000	6000	
Engine Cylinders Incorrect number of cylinders	6	8	

## Inspection Remarks:

FRONT LEFT SIDE/ SIDE FRAME MEMBER END/ BULKHEAD/FENDER /BONNET REPAIRED/ MINOR ENGINE OIL LEAK

## Payment Details

Inspection Performed by  
62439

Payment Method  
Cash

Transaction Number  
15496546

Service Fees  
AED 170 Collected on 20/11/2021

Parking Slot No  
--

Service Name  
Registration Test

Attempt  
1

Received by  
Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

