

Queue Number	2861369	Transaction Date	12 Oct 2026, 09:48:09
Site Name	840 - Emirates Auctions	Transaction Number	79860903 (CC10026) (CC10026)
		Vehicle Details Chassis Number 5XYPGDA59K***** Specification Imported Make Kia Model Sorento Model Year 2019 Color White Mileage 64603 Miles Fuel Type Petrol Transmission Type No. Of Cylinders 6	

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED , REAR RIGHT SIDE REPAINTED , FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	BOTH LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR , ENGINE , GEAR , CHASSIS COVERED CHECK VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN, PORTION GRILL LOOSE , DAMAGE	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , MISALIGN	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME , FENDER FRAME , BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL , BUMPER FRAME , RIGHT SIDE WHEEL ARCH REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاسي
02.A Chassis Extension	RIGHT SIDE OUTER CHASSIS EXTENSION REPAIRED	تمديدات الشاسي
02.B Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED , DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , ABNORMAL NOISY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , OIL LEAK DRIPPING , MINOR JERKING	الحالة النظرية للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED , RIGHT SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.C Fog light	NOT WORKING	كشاف الضباب
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	FRONT LEFT SIDE REPAIRED & BOOT CRACK	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	SIDE VIEW MIRROR OUTER HOUSING PORTION SCRATCHES , LEFT SIDE OUTER COVER MISSING	المرآيا
10.C AC Condition	OK	المكيف
10.D Roof Light	CONTROL SWICTH NOT WORKING PROPERLY	أنارة السقف
10.E Dash Board	PORTION WORN OUT	لوحة القيادة
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	PORTION WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات
10.I Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae