



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 16 Sep 2022, 11:14:19 |
| Transaction Number | 64297945 (CC10009) | Queue Number | 592023 |



| | |
|------------------|--------------------------|
| Chassis Number | WBAFG8102BL286693 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | BMW |
| Model | X6 |
| Model Year | 2011 |
| Color | White |
| Mileage | 178280 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------|--|------------------------|
| 01 Engine Condition | | المحرك |
| 01.A Smoke | WHITE SMOKE | دخان |
| 01.B Visual Engine Condition | MINOR OIL LEAK & REFITTED | حالة المحرك النظري |
| 02 Body | | جسم المركبة |
| 02.A Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION RUSTY | الصبغ |
| 02.B Fenders | FRONT FIBER PAINT CANNOT CHECK & REAR BOTH SIDE PORTION REPAIRED,REPAINTED | مدكار |
| 02.C Doors | FRONT LEFT SIDE & REAR BOTH SIDE PORTION REPAIRED,REPAINTED | أبواب |
| 02.D Bonnet | REFITTED | غطاء المحرك |
| 02.E Floor | FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY | الارضية |
| 03 Interior Condition | | الحالة الداخليه |
| 03.A AC Condition | OK & GRILL ADJUSTMENT BUTTON MISSING | المكيف |
| 03.B Door Panel | PORTION MELTED | لوحة بطانة الباب |
| 03.C Roof Ceiling | LOOSE | بطانه السقف |
| 03.D Other | CENTER CUP CONSOLE BOX SLIDING COVER MISSING | اخرى |

| DEFECT | REMARKS | |
|------------------------------------|---|---------------------|
| 03.E Mirror | LEFT SIDE ADJUSTMENT NOT WORKING PROPERLY | المرايا |
| 04 Tires and Rims Condition | | الاطارات |
| 04.A Front Tyre | BOTH SIDE 2020 | الاطار الامامي |
| 04.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 04.C Rims Condition | RIMS HAVE DENT SCRATCHES | حالة الجنوط |
| 05 Transmission Condition | | الجير |
| 05.A Visual Gear Box Condition | MINOR OIL LEAK & REFITTED | حالة الجير النظرى |
| 05.B Road Test | NOT CHECK | فحص علي الطريق |
| 06 Chassis Condition | | الشاصي |
| 06.A Chassis | CHECKED VISIBLE AREA OK | الشاسيه |
| 06.B Chassis Number | MANUFACTUR VIN STICKER DAMAGED | رقم القاعدة |
| 07 Brake Condition | | الفرامل |
| 07.A Hand Brake | SWITCH BUTTON LOOSE | فرامل اليد |
| 08 Steering Condition | | المقود |
| 08.A Tie Rod End | BOOT CUT | مؤخرة الروداد |
| 09 Suspension System | | ممتص الصدمات |
| 09.A Ball Joint | BOOT CUT | مفصل كروي |
| 09.B Arms | LOWER ARM BUSH CUT | ازرع |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.