




## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Aug 2022, 13:16:33</b>
Transaction Number	<b>49547885 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTDEPRAE9LJ007396</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Corolla</b>
Model Year	<b>2020</b>
Color	<b>Silver</b>
Mileage	<b>44373 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Air Bag	DAMAGED	وسائد هوائية
01.B AC Condition	OK	المكيف
01.C Sun Visor	RIGHT SIDE LOOSE	حاجب الشمس
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Pillars	PILLAR OUTER PANEL ,LEFT QUARTER PANEL REPAIRED,REPAINTED	القوائم
03.B Sign of side accident		وجود مؤشر لحادث في الجانب
03.C Paint	BODY TOTALY REPAINTED REPAIRED,MINOR DENT,SCRATCHES	الصبغ
03.D Sign of front accident		وجود مؤشر لحادث في المقدمة
03.E Fenders	FRONT BOTH SIDE REFITTED	مدكار
03.F Bonnet	REFITTED	غطاء المحرك
03.G Bumper	MISALIGN.FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD RPAIRED	دعامية

DEFECT	REMARKS	
03.H Doors	FRONT RIGHT SIDE DOOR REPLACED.	أبواب
03.I Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY.	صدأ
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OIL LEAK,	حالة المحرك النظرى
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	FRONT SUSPENSION REFITTED.	ازرع
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	FRONT LEFT SIDE CHASSIS BEND .	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Custom Certificate :	13037545
Chassis No :	JTDEPRAE9LJ007396
Vehicle Make :	TOYOTA
Vehicle Model :	COROLLA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	71403 Kms.
Origin : Japan	Model Year : 2020
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : NIL	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 1600 Kgs.	Empty 1150 Kgs.
	Weight :

Certificate Number :	5-SHA-2022-17159107		
Inspection Date :	06-07-2022		
Certificate Print Date :	06-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Shamil		
Vehicle Testing Center :	Shamil Al Qusais		
Total Time Taken :	9 min 25 sec		
Appointment Ref Number :	--		
Start Time :	11:47	End Time :	11:56
Lane :	02	Token No. :	161
Attempt :	1	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

14280 KM	1015 L	3188 AED	2.5 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 12 %	Service brake imbalance on rear axle 22 %	Parking brake imbalance between LHS and RHS 20 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 0 PPM VOL			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2000	1800	

## Inspection Remarks:

BULKHEAD RADIATOR FRAME FENDER FRAME LEFT SIDE WHEEL ARCH LEFT SIDE C PILLAR QUARTER PANEL REPAIRED

## Payment Details

Inspection Performed by 20569 15741	Payment Method Cash	Transaction Number 17159107	Service Fees AED 170 Collected on 06/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Ahmed Abdelmonem AbdelBodel Amin Elmasid

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

