



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 May 2023, 11:17:26**
 Transaction Number **80193257 (CC10008)** Queue Number **726109**



Chassis Number **WDDHF7CB3BA267577**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Mercedes**
 Model **E 500**
 Model Year **2011**
 Color **Black**
 Mileage **313793 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **Imported**

DEFECT	REMARKS	
01 Transmission Condition الجير		
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Propeller Shaft	FLANGE RUBBER CRACKED	ناقل الحركة
01.C Visual Gear Box Condition	OIL LEAK,REFITTED	حالة الجير النظري
02 Engine Condition المحرك		
02.A Other	AIR FILTER PIPE MISSING	اخرى
02.B Visual Engine Condition	MINOR OIL LEAK,REFITTED,HOUSING CASE BOLT ONE LOOSE	حالة المحرك النظري
03 Exhaust System نظام العادم		
03.A Other	EXHAUST MODIFIED,NOISY	اخرى
03.B Modification	EXHAUST MODIFIED& REAR MUFFLER MISSING ,NOISY,EXHAUST PIPE REWELDED	تعديلات
04 Interior Condition الحالة الداخلية		
04.A AC Condition	OK	المكيف
04.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
04.C Roof Ceiling	PORTION LOOSE	بطانة السقف

DEFECT	REMARKS	
04.D Sun Visor	DAMAGED	حاجب الشمس
04.E Other	CENTER CONSOLE BOX NOT OPEN PORTIO WORN OUT,CUP CONSOLE BOX SLIDING COVER NOT WORKING	اخرى
04.F Power Window Switch	BUTTON FADED	مفتاح النافذه
05 Body		جسم المركبة
05.A Doors	REAR RIGHT SIDE REPAINTED,PORITION REPAIRED	أبواب
05.B Fenders	REAR RIGHT SIDE REPAINTED,PORITION REPAIRED & FRONT REFITTED,UPPER COVER MISSING	مدكار
05.C Paint	BODY PORTION REPAIRED,REPAINTED,MINOR DENT,SCRATCHES,PORITION FADED,PORITION STICKER	الصبغ
05.D Floor	PORITION DENT,FLOOR COVER DAMAGED,COVER PART MISSING	الارضية
05.E Bonnet	HAVE STICKER PAINT CANNOT CHECK,REFITTED	غطاء المحرك
05.F Bumper	MISALIGN	دعامية
05.G Sign of front accident		وجود مؤشر لحادث في المقدمة
06 Tires and Rims Condition		الاطارات
06.A Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
06.B Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
06.C Rear Tyre	BOTH SIDE 2020,CRACKED	الاطار الخلفي
06.D Front Tyre	BOTH SIDE 2020,CRACKED	الاطار الامامي
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES MINOR CRACKED	ازرع
08 Chassis Condition		الشاصي
08.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
09 Steering Condition		المقود
09.A Axle	BOOT CUT ,GREASE LEAK	اكسلات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	REPAIRED	خزان التبريد
11 Seats Condition		المقاعد
11.A Seat Condition	FRONT SEAT HAVE EXTRA COVER	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

fitness for registration.