



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	04 Mar 2023, 12:48:56
Transaction Number	81132418 (CC10006)	Queue Number	682206



Chassis Number	SCBFE6ZA0FC043015
Engine Number	
Vehicle Class	Car
Manufacturer	Bentley
Model	Continental
Model Year	2015
Color	Grey
Mileage	111775 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	REFITTED	مدكار
01.B Paint	REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES ON BODY	الصبغ
01.C Sign of back accident		وجود مؤشر لحادث في الخلف
01.D Sign of side accident		وجود مؤشر لحادث في الجانب
01.E Pillars	BEDDING COVER LOOSE	القوائم
01.F Bumper	FRONT BULK HEAD REPAIRED BUMPER MISS ALIGN,GRILL CRACKED	دعامية
01.G Other	REAR COMPARTMENT ,QUATAR PANEL ,SPARE WHEEL HOUSING,BACK PANEL REPAIRED	اخرى
01.H Trunk	REPAIRED, REFITTED	صندوق
01.I Floor	UNDER FLOOR COVERED , CHECKED VISIBLE AREA ,PORTION DENT	الارضية
01.J Sign of front accident		وجود مؤشر لحادث في المقدمة
01.K Bonnet	REFITTED	غطاء المحرك
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	OK	حالة الجير النظري

DEFECT	REMARKS	
02.B Road Test	NOT CHECK	فحص علي الطريق
02.C Gear Box Mount	BRACKET DAMAGED	كرسي الجير
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Arms	FRONT LOWER ARM BUSHES CUT	ازرع
03.B Suspension Subframe	FRONT SUB/FRAME , INTER COOLER BRACKET DENT	
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Smoke	BLACK SMOKE	دخان
04.B Visual Engine Condition	ABNORMAL NOISY	حالة المحرك النظري
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	REAR RIGHT SIDE CHASSIS REPAIRED	الشاسيه
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
<b>07 Interior Condition</b>		<b>الحاله الداخليه</b>
07.A Sun Visor	RIGHT SIDE STAND CRACKED	حاجب الشمس
07.B AC Condition	OK	المكيف
07.C Roof Ceiling	LOOSE	بطانه السقف
07.D Door Panel	LOOSE	لوحة بطانة الباب

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



✓ PASS

Vehicle  
Registration



RTA

Plate Details :	Q 19352 Dubai Private
Chassis No :	SCBFE6ZA0FC043015
Vehicle Make :	BENTLEY
Vehicle Model :	CONTINENTAL
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	111776 Kms.
Origin : Great Britain	Model Year : 2015
Gear Type : Automatic	Engine Size : 4000 CC
Engine No : NIL	Horse 575
Axles No : 2	Power :
No Of 2	Cylinders : 12
Doors :	No Of Seats : 4
G. V. W. : 2200 Kgs.	Empty 1750 Kgs.
	Weight :

Certificate Number :	5-TAS-2023-18986158
Inspection Date :	09-03-2023
Certificate Print Date :	09-03-2023
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	13 min 12 sec
Appointment Ref Number :	--
Start 14:05	End Time : 14:18
Time :	Token No. : 185
Lane : 01	Prints No : 1
Attempt : 1	

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

3068 KM	316 L	1088 AED	0.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 0 %	Service brake imbalance on rear axle 2 %	Parking brake imbalance between LHS and RHS 2 %	Vehicle on Petrol CO Reading 0.32 %
Vehicle on Petrol HC Reading 149 PPM VOL			

## Inspection Remarks:

REAR RIGHT SIDE CHASSIS & EXTENSION @ LOADING AREA, REAR RIGHT SIDE QUARTER PANEL, TRUNK PANEL, WHEEL ARC AREA, SPARE WHEEL HOUSING AREA, FRONT BUMPER, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED

## Payment Details

Inspection Performed by 30544	Payment Method VTP Credit Account	Transaction Number 18986158	Service Fees AED 170 Collected on 09/03/2023
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

