





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21802990	Plate Category	: PRIVATE
Transaction Date	: 21 OCT 2020 10:14:34	Plate Number	: 9682 EA
Queue Number	: 238784	Import Doc. Ref.	:
Chassis Number	: MR2B29F33H1019682	Manufacturer/Model	: TOYOTA/YARIS
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
		FRONT SUSPENSION REFITTED / SUSPENSION NOISE
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
		BRAKE ROTORS RUSTY / BRAKE VIBRATIONS
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TIRES DOT 2020
05 Body		الهيكل
05.02 - Paint		الصبغ
		BODY SCRATCHES & DENTS
05.05 - Bumpers		الدعامية
		REPAIRED/ REFITTED / MISALIGN
05.08 - Chassis (Frame)		الشاصية
		REAR LEFT SIDE MEMBER END REPAIRED & DENT/ RIGHT SIDE MEMBER END DENT
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرايا الجانبية
		LEFT MIRROR FAULTY (NO UP/ DOWN ADJUSTMENT)
06.14 - Transmission Condition		حالة ناقل الحركة
		OK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		121379 KMS
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
		FRONT LEFT FENDER BRACKET REPAIRED/ FENDER REPLACED
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
		REAR LEFT QUARTER PANEL / BACK PANEL REPAIRED



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21802990	Plate Category	: PRIVATE
Transaction Date	: 21 OCT 2020 10:14:34	Plate Number	: 9682 EA
Queue Number	: 238784	Import Doc. Ref.	:
Chassis Number	: MR2B29F33H1019682	Manufacturer/Model	: TOYOTA/YARIS
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.24 - Digital Display Damaged/Warning Lights	TPMS LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صنيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية</p>		

Test Certificate



Vehicle
Registration



RTA

✓ PASS

Plate Details :	--
Chassis No :	MR2B29F33H1019682
Vehicle Make :	TOYOTA
Vehicle Model :	YARIS
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Red
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	121381 Kms.
Origin :	Thailand
Model Year :	2017
Gear Type :	Automatic
Engine No. :	2NR5007152
Engine Size :	1500 CC
Axes No. :	2
Horse Power :	107
No Of Doors :	4
Cylinders :	4
G. V. W. :	1600 Kgs.
Empty Weight :	1124 Kgs.
No Of Seats :	5

Certificate Number :	5-TAS-2020-12825771
Inspection Date :	24-10-2020
Certificate Print Date :	24-10-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	8 min 27 sec
Appointment Ref Number :	--
Start Time :	15:38
End Time :	15:46
Lane :	01
Token No. :	8
Attempt :	1
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

46 KM	3 L	5 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
1 %	12 %	5 %	0 %
Vehicle on Petrol HC Reading			
23 PPM VOL			

Inspection Remarks:

REAR LEFT SIDE MEMBER END REPAIRED & DENT/ RIGHT SIDE MEMBER END DENT// FRONT LEFT FENDER BRACKET REPAIRED/ FENDER REPLACED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460	VTP Credit Account	12825771	AED 170 Collected on 24/10/2020
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Raul Canceran Galang

① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

