




## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Sep 2022, 12:00:16</b>
Transaction Number	<b>96782282 (CC10009)</b>	Queue Number	<b>594483</b>



Chassis Number	<b>MRODX8CD3H0400951</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hilux</b>
Model Year	<b>2017</b>
Color	<b>White</b>
Mileage	<b>264154 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.B Fog light	NOT WORKING,LENS FADED	كشاف الضباب
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	NOT WORKING & RIGHT SIDE GRILL COVER LOOSE	المكيف
02.B Steering Wheel and control buttons	MINOR WORN OUT	عجلة القيادة وازرار التحكم
02.C Mirror	BOTH SIDE COVER LOOSE ,LEFT SIDE PORTION DAMAGED	المرايا
02.D Dash Board	HAVE EXTRA COVER	لوحة القيادة
<b>03 Seats Condition</b>		<b>المقاعد</b>
03.A Seat Condition	SEATS HAVE EXTRA COVER & COVER PORTION DAMAGED,DRIVER SEAT SIDE COVER LOOSE	حالة المقاعد
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
04.B Bumper	MISALIGN,PORTION CRACKED	دعامية
04.C Rusty	UNDER FLOOR PARTS CHASSIS THICK RUST PROOFED , PORTION RUSTY	صدأ

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
06.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Shock Absorber	FRONT BOTH SIDE LEAK	ممتص الصدمات
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Arms	LOWER ARM BUSHES CUT	ازرع
07.D Leaf Spring	BUSHES CUT	
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	CHASSIS FRAME THICK RUST PROOFED , PORTION RUSTY , OK	الشاسيه
<b>09 Transmission Condition</b>		<b>الجير</b>
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Visual Gear Box Condition	OK	حالة الجير النظري
09.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>11 Brake Condition</b>		<b>الفرامل</b>
11.A Hand Brake	LOOSE	فرامل اليد
11.B Brake Pedal	WEAK	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.