




## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 Nov 2022, 17:01:17</b>
Transaction Number	<b>17030362 (CC10006)</b>	Queue Number	<b>625181</b>



Chassis Number	<b>KMHDT41D3AU893529</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Hyundai</b>
Model	<b>Elantra</b>
Model Year	<b>2010</b>
Color	<b>Maroon</b>
Mileage	<b>180335 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Chassis Condition</b>		<b>الشاشي</b>
01.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION RUSTY WEAK & HOLE	الشاشيه
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	OIL WET	حالة المحرك النظري
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Tail Light	RIGHT SIDE FADED & CRACKED	الدائرة
03.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03.C Head Light	LENS FADED	الاضاءة الرئيسية
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Power Window Switch	RIGHT SIDE BOTH NOT WORKING	مفتاح النافذه
04.B Audio	COVER PORTION CRACKED	صوتيات
04.C Steering Wheel and control buttons	CRACKED	عجلة القيادة وازرار التحكم
04.D AC Condition	NOT COOLING	المكيف
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>

DEFECT	REMARKS	
05.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	OIL WET	حالة الجير النظرى
06.B Road Test	NOT CHECK	فحص علي الطريق
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Rusty	UNDER BODY PARTS, SUSPENTION, CHASSIS GETTING RUSTY	صدأ
07.B Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
07.C Fenders	REFITTED	مدكار
07.D Bonnet	REFITTED	غطاء المحرك
<b>08 Seats Condition</b>		<b>المقاعد</b>
08.A Seat Belt	REAR BOTH SIDE NOT WORKING	حزام الأمان
<b>09 Battery Condition</b>		<b>حالة البطارية</b>
09.A Battery bracket	MISSING	حامل البطارية
<b>10 Suspension System</b>		<b>ممتص الصدمات</b>
10.A Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	--
Chassis No :	KMHDT41D3AU893529
Vehicle Make :	HYUNDAI
Vehicle Model :	ELANTRA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Marone
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	180337 Kms.
Origin : South Korea	Model Year : 2010
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : G4GC9668287	Horse 140
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 1800 Kgs.	Empty 1450 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18209847
Inspection Date :	29-11-2022
Certificate Print Date :	29-11-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 47 sec
Appointment Ref Number :	--
Start Time : 16:20	End Time : 16:30
Lane : 01	Token No. : 234
Attempt : 1	Prints No : 1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
9 %	52 %	1 %	0 %

Vehicle on Petrol HC Reading  
0 PPM VOL

## Inspection Findings

Defects	Issue	Severity
Dip beams( Low Beams) headlight <b>CLEAN HEAD LIGHTS &amp; TAIL LIGHT FADED</b>	Lens cracked, broken or faded	Major
Service brake imbalance on rear axle	More than 30% imbalance between LHS and RHS	Major
Engine <b>LOWER MOUNTING CRACKED</b>	Worn out rubber mountings	Major
Engine <b>REPAIR OIL LEAK &amp; WASH UNDERNEATH</b>	Oil leaking continuously	Major

Inspection Remarks: UNDERNEATH MINOR RUSTY REAR LEFT SIDE EXTENSION END MINOR BULGED RUSTY

## Payment Details

Inspection Performed by 31339	Payment Method Cash	Transaction Number 18209847	Service Fees AED 170 Collected on 29/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Shawkat Mohamed Samir

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

