



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 Jan 2023, 15:35:20
Transaction Number	63734500 (CC10010)	Queue Number	657764



Chassis Number	JN1FN61C35W084457
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sunny
Model Year	2005
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Roof Light	SUNGLASS CONSOLE BOX DAMAGED	أنارة السقف
01.B Door Panel	PORTION DAMAGED	لوحة بطانة الباب
01.C Other	CENTER CONSOLE BOX DAMAGED,GEAR KNOB PORTION WORN OUT	اخرى
01.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.E Dash Board	PORTION DAMAGED,CONSOLE BOX DAMAGED	لوحة القيادة
01.F Odometer reading	NOT CHECK	قراءة عداد المسافات
01.G AC Condition	NOT CHECK	المكيف
02 Engine Condition		المحرك
02.A Mount	CRACKED	كرسي
02.B Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK ,REFITTED	حالة المحرك النظري
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box Mount	CUT	كرسي الجير
03.C Visual Gear Box	NOT CHECK,OIL LEAK REFITTED	حالة الجير النظري

DEFECT	REMARKS	
Condition		
04 Body		جسم المركبة
04.A Floor	PORTION DENT	الارضية
04.B Fenders	FRONT REFITTED	مدكار
04.C Sign of side accident		وجود مؤشر لحادث في الجانب
04.D Rusty	UNDER BODY PARTS SUSPENSION RUSTY	صدأ
04.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
04.F Other	REAR BACK PANEL,QUATER PANEL,SPARE WHEEL HOUSING,WHEEL ARCH,COMPARTMENT FLOOR REPAIRED	اخرى
04.G Sign of back accident		وجود مؤشر لحادث في الخلف
04.H Bonnet	REFITTED	غطاء المحرك
04.I Paint	BODY REPAINTED REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY	الصبغ
04.J Pillars	RIGHT SIDE C/PILLAR,ROCKER PANEL,RUNNING BOARD,WHEEL ARCH REPAIRED	القوائم
05 Steering Condition		المقود
05.A Steering Boot	BOOT CUT	ربلة المقود
05.B Axle	BOOT CUT	اكسلات
05.C Steering Oil	OIL LEAK	زيت المقود
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2020,CRACKED	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
07 Suspension System		ممتص الصدمات
07.A Ball Joint	BOOT CUT	مفصل كروي
07.B Arms	LOWER ARM BUSH CRACKED	ازرع
07.C Other	STABILIZER LINK BOOT CUT	اخرى
07.D Shock Absorber	LEAK	ممتص الصدمات
08 Lights		الاضاءة
08.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
09 Chassis Condition		الشاسي
09.A Chassis	REAR BOTH SIDE CHASSIS REPAIRED,BEND	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Car Check does not guarantee the vehicle's fitness for registration.