

Queue Number

2877637

Transaction Date

17 Oct 2026, 12:14:36

Site Name

840 - Emirates Auctions

Transaction Number

78360572 (CC10013) (CC10025)



Vehicle Details

Chassis Number	WD4WA6A69E*****
Specification	GCC Specification
Make	Mercedes
Model	Viano
Model Year	2014
Color	Black
Mileage	94103 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR RGHT SIDE STRAP MISSING , PORTION DENTS	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS SCRATCHES , PORTION FADED , PAINT PORTION DAMAGED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUNNING BOARD DENT BEND	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGED	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED REFITTED	غطاء المحرك
01.G Trunk	REPAINTED PORTION REPAIRED , SHOCK NOT WORKING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY OILY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL PAN DENT , REFITTED , PARTS GETTING RUSTY , ABNORMAL NOISY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION BDAMAGED SIDE COVER LOOSE , DRIVER SEAT ADJUSTMENT NOT WORKIG PROPERLY , RONT RIGHT SIDE ADJUSTMENT LOOSE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	REAR MOUNT RUBBER CRACK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	SPARE MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	SWITCH PANEL DAMAGED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT MESSAGE ON DISPLAY	ضوء تحذير
07.C Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	MINOR LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	BOTH SIDE PORTION LOOSE	المرايا
09.C AC Condition	NOT COOLING , GRILL PORTION DAMAGED	المكيف
09.D Power Window Switch And Glass	MAIN SWITCH COVER DAMAGED MISSING	مفتاح النافذه و الزجاج
09.E Audio	SCREEN PORTION FADED	صوتيات
09.F Dash Board	CENTER BOX COVER DAMAGED	لوحة القيادة
09.G Roof Ceiling	LOOSE	بطانه السقف
09.H Sun Visor	BOTH SIDE DAMAGED REPAIRED , MIRROR COVER MISSING	حاجب الشمس
09.I Door Panel	PORTION DAMAGED LOOSE	لوحة بطانة الباب
09.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.K Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae