

TEST CERTIFICATE

الحاله الداخليه

Site Number
Transaction Number

02 Interior Condition

840-Emirates Auctions 44713940 (CC10006) Transaction Date

28 Dec 2021, 17:52:53

Queue Number

312309



Chassis Number MR0FX22G9B1328821

Engine Number

Vehicle Class Heavy
Manufacturer Toyota
Model Hilux
Model Year 2011

Color White

Mileage **476412 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

O1 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE PORTION REPAIRED & RIGHT SIDE REPAINTED	مدكار
01.B Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.C Floor	REAR CARRIOR BOX PORTION REPAIRED & REPAINTED	الارضية
01.D Doors	REAR RIGHT SIDE CABIN PORTION REPAINTED	أبواب
01.E Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS , FLOOR GETTING RUSTY, WEAK	صدأ
01.F Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.G Bumper	REPAINTED, MISALIGN & GRAIL LOOSE	دعامية
01.H Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخري

02.A Dash Board INNER BOX COVER MISSING لوحة القياده عندان المعادر القيادة ال

O2.B AC Condition NOT COOLING

المساحات O3 Wipers and Arms

O3.A Wiper Arm &Blade RIGHT SIDE BLADE MISSING ازرع المساحات والشفرات

DEFECT	REMARKS	
04 Lights		الاضاءة
04.A Head Light	OK	الاضاءة الرئيسية
05 Seats Condition		المقاعد
05.A Seat Condition	FRONT BOTH SIDE PORTION DAMAGED	حالة المقاعد
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06.C Rims Condition	RUSTY	حالة الجنوط
07 Chassis Condition		الشاصي
07.A Chassis	CHASSIS FRAME COMPLETLY RUSTY & WEAK, HOLE, DAMAGED	الشاسيه
08 Engine Condition		المحرك
08.A Engine Condition	OIL LEAK	حالة المحرك
08.B Mount	BUSHES CRACKED	كرىسي
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OIL LEAK	الجير
09.C Gear Box Mount	BUSHES CRACKED	كرىسي الجير
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
10.B Leaf Spring	BOTH SIDE BUSHES CUT & LEAF GETTING RUSTY	
10.C Suspension Subframe	SUSPENTION SUB FRAME, BODY MOUNT, CROSS MEMBER RUSTY & WEAK	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.