



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	29 Apr 2022, 11:35:59
Transaction Number	34905738 (CC10008)	Queue Number	312309



Chassis Number	2FMDK49C49BA43313
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Edge
Model Year	2009
Color	Black
Mileage	120758 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED & DENTS , SCRATCHES ON BODY	الصبغ
01.B Fenders	REPAINTED , REPAIRED	مدكار
01.C Bonnet	REFITTED	غطاء المحرك
01.D Doors	DOOR PORTION REPAINTED	أبواب
01.E Other	FROTN BUMPER FRAME BULK HEAFD FENDER FRAME REPAIRED	اخرى
01.F Roof	ROOF PORTION REPAINTED	السقف
01.G Floor	UNDER FLOOR TOO OILY	الارضية
01.H Door Handle &Lock	FRONT RIGHT SIDE INNER DOOR HANDLE BROKEN	مقابض الأبواب والأقفال
01.I Sign of front accident		وجود مؤشر لحادث في المقدمة
02 Interior Condition		الحالة الداخلية
02.A Power Window Switch	REAR LEFT SIDE NOT WORKING	مفتاح النافذه
02.B AC Condition	OK	المكيف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي

DEFECT	REMARKS	
03.B Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
04 Transmission Condition		الجير
04.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
04.C Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	REAR LEFT SIDE LEAK	ممتص الصدمات
06.B Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
06.C Ball Joint	BOOT CUT	مفصل كروي
06.D Other	STABILIZER LINK BOOT CUT	اخرى
07 Chassis Condition		الشاشي
07.A Chassis	FROTN LEFT SIDE CHASSIS REPAIRED/ RIGHT SIDE TOO OILY & MUDDY CLEAN FOR RECHECK PROPERLY	الشاسيه
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
09 Engine Condition		المحرك
09.A Visual Engine Condition	OIL LEAK , REFITTED	حالة المحرك النظري
10 Seats Condition		المقاعد
10.A Seat Condition	PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	66442059
Chassis No :	2FMDK49C49BA43313
Vehicle Make :	FORD
Vehicle Model :	EDGE
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	120759 Kms. x
Previous Odometer Reading :	196239 Kms.
Origin : Canada	Model Year : 2009
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : 9BA43313	Horse Power : 263
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2500 Kgs.	Empty Weight : 1800 Kgs.

Certificate Number :	5-TAS-2022-16692047
Inspection Date :	28-04-2022
Certificate Print Date :	28-04-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	12 min 16 sec
Appointment Ref Number :	--
Start Time : 13:20	End Time : 13:33
Lane : 03	Token No. : 172
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 18 %	Service brake imbalance on rear axle 14 %	Parking brake imbalance between LHS and RHS 10 %	Vehicle on Petrol CO Reading 0.37 %
Vehicle on Petrol HC Reading 115 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Tie-rod, Bushes, Center Link CHANGE TIE ROD END BUSHES WORN OUT	Excessive wear or defective tie-rod, bushes or link	Major
Arm, mounting, bushes CHANGE FRONT LOWER ARM BUSHES	Worn-out bushes	Major
Shock Absorber CHANGE REAR LEFT SIDE & FRONT RIGHT SIDE SHOCK ABSORBERS	Major leak	Major
Engine REPAIR ENGINE OIL LEAK	Oil leaking continuously	Major

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks:

FRONT BOTH SIDE CHASSIS HEATED REPAIRED CCM OK W/O/#20180808-010,DATED 08/08/2018 FILED..FRONT BUMPER FRAME,BULK HEAD,RADIATOR SUPPORT REPAIRED.OLD



Odometer Record
Replace Events Date

28/04/2022

Payment Details

Inspection Performed by 34439	Payment Method Cash	Transaction Number 16692047	Service Fees AED 170 Collected on 28/04/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

i This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.



تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.