

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 75927718 (CC10006) Transaction Date

18 Oct 2021, 17:19:58

Queue Number 312309

Chassis Number

SALLSAAD4AA233820

Engine Number

Car

Vehicle Class Manufacturer

Range Rover

Model

--

Model Year

2010

Color

White

Mileage

98704 Km

Fuel Type

Petrol

No. Of Cylinders

0

Specification

GCC Specification

DEFECT REMARKS

| O1 Body | | جسم المركبة |
|-----------------------|--|--------------|
| 01.A Paint | BODY PORTION REPAINTED, PORTION REPAIRED | الصبغ |
| 01.B Fenders | FRONT BOTH &REAR RIGHT REPAINTED, PORTION REPAIRED | مدكار |
| 01.C Doors | RIGHT DOOR REPAINRED, REFITIED | أبواب |
| 01.D Bonnet | REPAINTED | غطاء المحرك |
| 01.E Trunk | SHOCK STAND WEAK NOT WORKING | صندوق |
| 01.F Floor | RIGHT RUNNING BOARD, ROCKER PANEL REPAIRED | الارضية |
| 01.G Pillars | RIGHT B/PILLAR POST REPAIRED | القوائم |
| 01.H Rusty | UNDER BODY PARTS, CHASSIS GETTING MINOR RUSTY | صدأ |
| 02 Suspension System | | ممتص الصدمات |
| 02.A Shock Absorber | CENTER CONTROL BOTTON HYDRAULIC SYSTEM &OTHER SYSTEM NOT WORKING | ممتص الصدمات |
| 02.B Other | FRONT TIRE MISALIGMENT | اخري |
| 02.C Coil Spring | BODY LEVEL LOW | ياي حلزوني |
| 03 Steering Condition | | المقود |
| 03.A Other | CROSS CONTROL BOTTON NOT WORKING | اخري |
| | | احري |

| DEFECT | REMARKS | |
|-----------------------------|--|------------------------|
| 03.C Steering Oil | OIL LEAK | زيت المقود |
| 04 Interior Condition | | الحاله الداخليه |
| 04.A Roof Ceiling | REAR ROOF CELING LOSE NOT FIX PROPERLY | بطانه السقف |
| 04.B AC Condition | ОК | المكيف |
| 05 Seats Condition | | المقاعد |
| 05.A Seat Belt | ОК | حزام الأمان |
| 05.B Seat Condition | OK | حالة المقاعد |
| 06 Lights | | الاضاءة |
| 06.A Warning Light | WARNING ON IN DISPLAY | ضوء تحذير |
| 06.B Head Light | RIGHT NOT WORKING | الاضاءة الرئيسية |
| 07 Chassis Condition | | الشاصي |
| 07.A Chassis | OK | الشاسيه |
| 08 Engine Condition | | المحرك |
| 08.A Engine Condition | OIL LEAK | حالة المحرك |
| 09 Transmission Condition | | الجير |
| 09.A Road Test | NOT CHECK | فحص علي الطريق |
| 09.B Gear Box | OK | الجير |
| 09.C Propeller Shaft | PROPELLER SHAFT BOOT CUT | ناقل الحركة |
| 10 Exhaust System | | نظام العادم |
| 10.A Other | OPEN&REWELDED,LEAK | اخري |
| 11 Wipers and Arms | | المساحات |
| 11.A Wiper Arm &Blade | WORN OUT | ازرع المساحات والشفرات |
| 12 Tires and Rims Condition | | الاطارات |
| 12.A Front Tyre | BOTH SIDE 2019 | الاطار الامامي |
| 12.B Rear Tyre | BOTH SIDE 2019 | الاطار الخلفي |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.