



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Sep 2021, 10:41:09
Transaction Number	21714015 (CC10006)	Queue Number	312309



Chassis Number	3GKFK16R3VG523567
Engine Number	
Vehicle Class	Car
Manufacturer	GMC
Model	Suburban
Model Year	1997
Color	White
Mileage	271034

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, FLOORING, CHASSIS GETTING RUSTY	صدأ
01.E Bumper	REPAINTED	دعامية
01.F Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.G Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED OLD	اخرى
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME COMPLETLY RUSTY & MIDDLE SLIGHTLY BEND	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Exhaust System		نظام العادم
05.A Other	WELDED & REPAIRED	اخرى
06 Transmission Condition		الجير

DEFECT	REMARKS	
06.A Gear Box	MINOR LEAK	الجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
08 Wipers and Arms		المساحات
08.A Other	WORN OUT	اخرى
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية
09.B Other	OK	اخرى
10 Brake Condition		الفرامل
10.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
11.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
12 Steering Condition		المقود
12.A Steering Box	OIL LEAK	جهاز المقود
12.B Tie Rod End	BUSHES CUT	مؤخرة الرودادات
12.C Other	STABILIZER LINK & CONTROL BAR BUSHES DRY CRACKED	اخرى
13 Interior Condition		الاجزاء الداخلية
13.A Other	BOTH SIDE SEAT BELT NOT WORKING	اخرى
13.B AC Condition	OK	المكيف
13.C Mirror	RIGHT SIDE STAND MIRROR REPAIRED	المرابا

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	3GKFK16R3VG523567
Vehicle Make :	GMC
Vehicle Model :	SUBURBAN
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White, Golden
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	271035 Kms.
Origin :	Mexico
Model Year :	1997
Gear Type :	--
Engine Size :	6600 CC
Engine No :	23567
Horse Power :	250
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	9
G. V. W. :	3629 Kgs.
Empty Weight :	1955 Kgs.

Certificate Number :	5-TAS-2021-15019292
Inspection Date :	15-09-2021
Certificate Print Date :	15-09-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	16 min 0 sec
Appointment Ref Number :	--
Start Time :	10:09
End Time :	10:25
Lane :	01
Token No. :	113
Attempt :	1
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

10038 KM	1033 L	1674 AED	2.5 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 10 %	Parking brake imbalance between LHS and RHS 37 %	Vehicle on Petrol CO Reading 1.3 %
Vehicle on Petrol HC Reading 229 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	9	8	

Inspection Remarks:

FIX PROPERLY REAR SEAT*/ MINOR GEAR&ENGINE OIL LEAK/ FRONT BUMPER/BULKHEAD/ FENDER /BONNET REPAIRED

Payment Details

Inspection Performed by --	Payment Method VTP Credit Account	Transaction Number 15019292	Service Fees AED 170 Collected on 15/09/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

