



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Jan 2023, 14:26:27
Transaction Number	73091866 (CC10010)	Queue Number	657857



Chassis Number	WVWZZZ9CZ2M616787
Engine Number	
Vehicle Class	Car
Manufacturer	Volkswagen
Model	Beetle
Model Year	2002
Color	Yellow
Mileage	216240 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Door Panel	PORTION DAMAGED	لوحة بطانة الباب
01.B AC Condition	LOW COOLING	المكيف
01.C Roof Light	SUNGLASS CONSOLE BOX DAMAGED	أنارة السقف
01.D Steering Wheel and control buttons	WORN OUT,HORN NOT WORK.	عجلة القيادة وازرار التحكم
01.E Other	CENTER CONSOLE BOX DAMAGED,GEAR LIVER DUST COVER MISSING .	اخرى
01.F Roof Ceiling	PORTION LOOSE	بطانه السقف
01.G Dash Board	PORTION DAMAGED,GLOVE BOX MISSING	لوحة القيادة
02 Seats Condition		المقاعد
02.A Seat Condition	PORTION DAMAGED	حالة المقاعد
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2019 CRACKED, WORN OUT	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHTS ON DISPLAY.	ضوء تحذير

DEFECT	REMARKS	
04.B Brake Light	RIGHT SIDE NOT WORKING.	نور الفرامل
04.C Head Light	LENS FADED	الاضاءة الرئيسية
05 Body		جسم المركبة
05.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
05.B Other	LEFT SIDE QUATER PANEL DAMAGED	اخرى
05.C Fenders	FIBER PAINT CANNOT CHECK & FRONT RIGHT SIDE PORTION DAMAGED	مدكار
05.D Bonnet	SHOCK WEAK,REFITTED,LOCK HANDLE DAMAGED	غطاء المحرك
05.E Rusty	UNDER BODY PARTS SUSPENSION RUSTY	صدأ
05.F Sign of side accident		وجود مؤشر لحادث في الجانب
05.G Floor	UNDER FLOOR,RUNNING BOARD DENT	الارضية
06 Engine Condition		المحرك
06.A Visual Engine Condition	OPEN,REFITTED,OIL LEAK,ABNORMAL NOISY	حالة المحرك النظرى
06.B Smoke	WHITE SMOKE .	دخان
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	REFITTED,OIL LEAK,JERKING.	حالة الجير النظرى
07.B Road Test	NOT CHECK	فحص على الطريق
08 Exhaust System		نظام العادم
08.A Other	EXHAUST CUT & REWELDED	اخرى
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
09.B Arms	LOWER ARM BUSH CUT	ازرع
09.C Shock Absorber	LEAK	ممتص الصدمات
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
10.B Steering Boot	BOOT CUT	ربلة المقود
10.C Axle	BOOT CUT	اكسلات
10.D Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Chassis Condition		الشاسي
11.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.