

#### **TEST CERTIFICATE**

الصبغ

Site Number Transaction Number

01.E Other

**840-Emirates Auctions** 

37028435 (CC10006)

27 Jun 2022, 11:16:12

Oueue Number

Chassis Number

WP1ZZZ92ZGLA78523

312309

Car

**Engine Number** 

Vehicle Class

Transaction Date

Manufacturer **Porsche** 

Model Cayenne

Model Year 2016

Color Black

Mileage 132066 Km

Fuel Type **Petrol** 

No. Of Cylinders

Specification **GCC Specification** 

REMARKS **DEFECT** 

01 Body جسم المركبة

01.A Doors	FRONT LEFT SIDE PORTION REPAIRED, REPAINTED	أبواب	
01.B Bonnet	PORTION REPAIRED, REPAINTED & REFITTED, SHOCKS	غطاء المحرك	
	WEAK		

01.C Trunk PORTION REPAIRED, REPAINTED صندوق

01.D Sign of front accident وجود مؤشر لحادث في المقدمة

FRONT BUMPER FRAME BULK HEAD FENDER FRAME اخری RADIATOR SUPPORT REPAIRED

01.F Paint **BODY REPAINTED PORTION REPAIRED MINOR DENTS** 

**SCRATCHES ON BODY** 

01.G Floor UNDER FLOOR CHASSIS FULLY COVERED CHECKED الارضية

**VISIBLE AREA** 

01.H Fenders FRONT BOTH SIDE PORTION REPAIRED, REPAINTED & مدكار

REFITTED, RIGHT SIDE FENDER SKIRT LOOSE

**02 Interior Condition** الحاله الداخلية

02.A AC Condition OK & GRILL ADJUSTMENT BUTTON MISSING المكيف 02.B Mirror VIEW MIRROR STAND COVER LOOSE المرايا

02.C Power Window Switch **RONT LEFT SIDE BUTTON DAMAGED** مفتاح النافذه

**03 Suspension System** ممتص الصدمات

DEFECT	REMARKS		
03.A Arms	LOWER ARM BUSHES CRACKED	ازرع	
04 Chassis Condition		الشاصي	
04.A Other	FOR RECHECK PROEPRLY REMOVE FENDERS COVERE	خري	
04.B Chassis	FRONT LEFT SIDE CHASSIS END REPAIIRED ,RIGHT SIDE OUTER MINOR DENT	لشاسيه	
05 Steering Condition		المقود	
05.A Axel	LEAK	اكسلات	
05.B Tie Rod End	BOOT CUT	مؤخرة الرودات	
06 Transmission Condition		الجير	
06.A Road Test	NOT CHECK	فحص علي الطريق	
06.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة الجير النظرى	
07 Tires and Rims Condition		الاطارات	
07.A Front Tyre	BOTH SIDE 2020/2021	لاطار الامامي	
07.B Rear Tyre	BOTH SIDE 2020/2021	لاطار الخلفي	
08 Engine Condition		لمحرك	
08.A Visual Engine Condition OIL LEAK REFITTED		حالة المحرك النظرى	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**











Change possession: 66645595 WP1ZZZ92ZGLA78523 Chassis No: Vehicle Make: **PORSCHE** Vehicle Model: **CAYENNE** Vehicle Class: Light Vehicle **Body Type:** STATION Fuel: Benzene Color: Black **Drive Direction:** Dimensions: (H x W x L) --x--x-**Current Odometer:** 132068 Kms. Origin: Model Year: 2016 Engine Size: 3600 CC Gear Type: Automatic Engine No: 007603 Horse 300 Power: Axles No: Cylinders: 6 No Of No Of Seats: 5 Doors: G. V. W. : 2300 Kas. **Empty** 1800 Kas. Weight:

Certificate Number :		5-CAR-2022-17111046			
Inspection Date :		29-06-2022			
Certificate Print Date :		29-06-2022			
Services :		Registration Test			
Vehicle Testing Partner:		AG Cars			
Vehicle Testing Center:		AG Cars Al Mamzar			
Total Time Taken:		8 min 14 sec			
Appointment Ref Number :					
Start	18:36		End Time:	18:44	
Time :			Token No.:	260	
Lane :	03		Prints No:	1	
Attempt:	1				

#### Carbon footprint




Thank you! You are environment protector

#### Vehicle Consumption (last 12 Months)



year





0.9 ton Fuel cost per Carbon footprint year per year

### **Parameter Readings**

Service brake imbalance on front axle 12 % Vehicle on Petrol HC

Service brake imbalance on rear axle 1%

Parking brake imbalance between LHS and RHS

**Vehicle on Petrol CO** Reading 0%

#### **Inspection Remarks:**

Reading O PPM VOL

FRONT LEFT SIDE FRAME MEMBER REPAIRED. HAVING PASSED CCM REPORT, FRONT BULKHEAD, BUMPER FRAME, RADIATOR FRAME REPAIRED.

# **Payment Details**

Inspection Performed by **Payment Method** Transaction Number **Service Fees** A06443 17111046 Cash AED 170 Collected on 29/06/2022 **Parking Slot No Service Name** Attempt Received by **Registration Test** Mary Antony

- 🐧 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- 1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. ..تخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.