



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **13 Sep 2021, 16:55:54**
 Transaction Number **58249281 (CC10006)** Queue Number **312309**



Chassis Number **JDA00F30000071595**
 Engine Number
 Vehicle Class **Heavy**
 Manufacturer **Daihatsu**
 Model **Feroza**
 Model Year **1993**
 Color **Green**
 Mileage **0**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS , FLOORING, CHASSIS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR FULLY RUST PROOFED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	PORTION REPAIRED , REPAINTED & BLASTIC	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED	الشاسيه
02.B Other	VIN NUMBER AREA GETTING RUSTY	اخرى
03 Engine Condition		المحرك
03.A Mount	BUSHES CUT	كرسي
03.B Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير

DEFECT	REMARKS	
05.A Gear Box	OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CUT	كرسي الجير
06 Wipers and Arms		المساحات
06.A Other	OK	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	WEAK & RUSTY	ممتص الصدمات
09.B Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
09.C Leaf Spring	BOTH SIDE BUSHES CUT & LEAF GETTING RUSTY	
10 Steering Condition		المقود
10.A Steering Box	OIL LEAK	جهاز المقود
10.B Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
10.C Axel	BOTH SIDE BOOT DRY CRACK	اكسلات
11 Interior Condition		الاجزاء الداخلية
11.A Other	OK	اخرى
11.B Mirror	OK	المرايا
11.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✗ FAILED

Plate Details :	--
Chassis No :	JDA00F30000071595
Vehicle Make :	DAIHATSU.
Vehicle Model :	FAYROZA
Vehicle Class :	Light Vehicle
Body Type :	JEEP
Fuel :	Benzene
Color :	White
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	231927 Kms.
Origin : Japan	Model Year : 1993
Gear Type : Automatic	Engine Size : 1500 CC
Engine No : 0405344	Horse Power : --
Axles No : 2	Cylinders : 4
No Of Doors : 2	No Of Seats : 4
G. V. W. : 1900 Kgs.	Empty Weight : 1200 Kgs.

Certificate Number :	5-TAS-2021-15022174
Inspection Date :	15-09-2021
Certificate Print Date :	15-09-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	22 min 44 sec
Appointment Ref Number : --	
Start Time : 13:44	End Time : 14:07
Lane : 01	Token No. : 153
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 1 %	Service brake imbalance on rear axle 11 %	Parking brake imbalance between LHS and RHS 12 %	Vehicle on Petrol CO Reading 5.8 %
Vehicle on Petrol HC Reading 557 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Vehicle on Petrol CO Reading	CO reading more than 4.5%	Major

Discrepancies	Old Value	New Value	Verified
Paint Changed Color	White	Green	
Vehicle Make - Registration Incorrect Make - Does Not Require Document	DAIHATSU.	DAIHATSU	
Vehicle Model - Registration Incorrect Model - Does Not Require Document	FAYROZA	FEROZA	
Engine Size Discrepancy in Engine Size	1500	1600	

Inspection Remarks: front left side chassis end repaired/minor engine oil&steering box oil leak

Payment Details

Inspection Performed by 62439	Payment Method VTP Credit Account	Transaction Number 15022174	Service Fees AED 170 Collected on 15/09/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

- ❗ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
❗ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

