

## **TEST CERTIFICATE**

الصبغ

Site Number **840-Emirates Auctions** Transaction Date 24 May 2023, 10:09:03

Transaction Number 49760979 (CC10010) Oueue Number 720319



Chassis Number 6T1BF9FK6EX530718

**Engine Number** 

Vehicle Class Car

Manufacturer Toyota

Model Camry

Model Year 2014

Color

Mileage 001 Km

Fuel Type Petrol

No. Of Cylinders

Specification **GCC Specification** 

**DEFECT** REMARKS

01 Body جسم المركبة

01.A Paint BODY PORTION REPAIRED, PORTION REPAINTED, DENTS

SCRATCHES, PORTION FADED, PORTION RUSTY. STICKER

DAMAGE, TAXI,

01.B Sign of back accident وجود مؤشر لحادث في الخلف

01.C Vehicle Color VIOLET .BIEGE. لون المركبة

01.D Other FRONT BUMPER FRAME, FENDER FRAME, BULKHEAD اخري ,RADIATOR SUPPORT REPAIRED. BACK PANEL ,QUARTER

PANEL REPAIRED.

MISALIGN, PORTION DAMAGE. 01.E Bumper دعامية

01.F Sign of front accident وجود مؤشر لحادث في المقدمة

01.G Rusty UNDER BODY, SUSPENSION PARTS GETTING RUSTY صدأ

PORTION DENT. 01.H Floor الارضية

01.I Bonnet DENT. غطاء المحرك

**02 Transmission Condition** الجير

02.A Road Test NOT CHECKED. فحص على الطريق

02.B Visual Gear Box NOT CHECKED , REFITTED OIL LEAK. حالة الجير النظرى

Condition

**03 Interior Condition** الحاله الداخليه

DEFECT	REMARKS	
03.A AC Condition	NOT CHECKED .	المكيف
03.B Other	HAND REST CRACKED.	اخري
03.C Steering Wheel and control buttons	WORN OUT ,CRACKED .	عجلة القيادة وازرار التحكم
03.D Odometer reading	NOT CHECKED.	قراءة عداد المسافات
04 Lights		الاضاءة
04.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM BUSHES CRACKED.	ازرع
05.B Shock Absorber	WEAK ,LEAK .	ممتص الصدمات
06 Steering Condition		المقود
06.A Steering Box	OIL LEAK,	جهاز المقود
06.B Axle	BOOT CUT.	اكسلات
07 Chassis Condition		الشاصي
07.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED ,BEND.	الشاسيه
08 Engine Condition		المحرك
08.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED .OIL LEAK.	حالة المحرك النظرى
08.B Mount	CUT.	كرسي
09 Tires and Rims Condition		الاطارات
09.A Rear Tyre	BOTH SIDE 2019 CRACKED.	الاطار الخلفي
09.B Front Tyre	BOTH SIDE 2019 CRACKED.	الاطار الامامى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.