

## **TEST CERTIFICATE**

Site Number 840-Emirates Auctions Transaction Date 05 Aug 2022, 12:05:58

Transaction Number 50892627 (CC10006) Queue Number 312309



Chassis Number JN8FY15Y59X570690

Engine Number

Vehicle Class Car

Manufacturer Nissan

Model Patrol

Model Year 2009

Color White

Mileage **376599 Km** 

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

Ol Engine Condition المحرك

O1.A Visual Engine Condition ENGINE NOT START ALL SYSTEM NOT CHECK , OIL LEAK , حالة المحرك النظرى REFITTED

O1.B Mount MOUNT RUBBER CUT

O2 Interior Condition الحاله الداخلية

O2.A AC Condition NOT CHECK

O2.B Steering Wheel and WORN OUT عجلة القيادة وازرار التحكم control buttons

ووتيات AUDIO SWITCH COVER MISSING

جسم المركبة جسم المركبة عند المركبة عند

مدكار 03.A Fenders FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED , FRONT

REFITTED & REAR RIGHT SIDE PORTION

REPAIRED, REPAINTED

O3.B Paint BODY PORTION REPAIRED , REPAINTED & MINOR DENT الصبغ

,SCRATCHES,PORTION GETTING RUSTY

أبواب 03.C Doors RIGHT SIDE REPAIRED,REPAINTED

O3.D Floor UNDER FLOOR THICK RUST PROOFED , MUDDY , FRONT الارضية

BOTH SIDE BODY MOUNT RUSTY REPAIRED , LEFT SIDE

FOOT STEP PORTION DAMAGED

DEFECT	REMARKS	
03.E Sign of front accident		وجود مؤشر لحادث في المقدمة
03.F Bonnet	REFITTED	غطاء المحرك
03.G Bumper	PORTION DAMAGED	دعامية
04 Tires and Rims Condition		الاطارات
04.A Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
04.B Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
04.C Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
05 Suspension System		ممتص الصدمات
05.A Shock Absorber	MODIFIED	ممتص الصدمات
05.B Arms	CONTROL ARM BUSHES CRACKED	ازرع
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	OIL LEAK,REFITTED	حالة الجير النظرى
06.B Road Test	NOT CHECK	فحص علي الطريق
06.C DIFFERENTIAL	OIL LEAK	الدفرنشل
06.D Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
07 Seats Condition		المقاعد
07.A Seat Condition	FRONT SEATS HAVE EXTRA COVER & REAR MISSING	حالة المقاعد
08 Chassis Condition		الشاصي
08.A Chassis	FROTN RIGHT SIDE CHASSIS DENT REAR BOTH SIDE BULGED	الشاسيه
08.B Chassis Number	CLEAN CHASSIS PUNCHING NUMBER NOT CLEAR , WINDSHIELD NUMBER MISSING	رقم القاعدة
09 Lights		الاضاءة
09.A Head Light	ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.