

Queue Number 2899754

Transaction Date 23 Oct 2026, 15:28:57

Site Name
840 - Emirates AuctionsTransaction Number
74366593 (CC10010) (CC10010)

Vehicle Details

Chassis Number	JMYLYV77W4*****
Specification	GCC Specification
Make	Mitsubishi
Model	Pajero
Model Year	2004
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS RUSTPROOFED PORTION DENT ,MUDDY ,OILY .,	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER PORTION CUT.	حالة المقاعد
---------------------	--------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED,	فحص علي الطريق

06 Tires and Rims Condition

الاطارات

06.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الامامي
-----------------	---------------------------------	----------------

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECKED.	المكيف
10.C Dash Board	PORTION LOOSE	لوحة القيادة
10.D Odometer reading	NOT CHECKED.	قراءة عداد المسافات
10.E Door Panel	WORN OUT PORTION LOSE	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT.,	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae