



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 Apr 2022, 12:28:42</b>
Transaction Number	<b>51583681 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTHBH965565026778</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Lexus</b>
Model	<b>GS 300</b>
Model Year	<b>2006</b>
Color	<b>White</b>
Mileage	<b>215830 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	LEFT SIDE 2019 CRACKED & RIGHT SIDE 2021	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
<b>02 Chassis Condition</b>		<b>الشاسيه</b>
02.A Chassis	REAR RIGHT SIDE CHASSIS & CHASSIS EXTENSION REPAIRED	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	MINOR OIL LEAK ,SHAKING	حالة المحرك النظري
03.B Smoke	WHITE SMOKE	دخان
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C DIFFERENTIAL	REAR DIFFERENTIAL SIGN OF OIL LEAK	الدفرنشيل
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED, PORTION REPAIRED	مدكار

DEFECT	REMARKS	
05.B Trunk	REPAINTED,PORTION REPAIRED,REFITTED	صندوق
05.C Bonnet	SHOCK WEAK	غطاء المحرك
05.D Doors	FRONT LEFT SIDE &RIGHT SIDE BOTH DOOR REPAINTED,PORTION REPAIRED	أبواب
05.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
05.F Floor	BACK PANEL ,COMPARTMENT ,QUATER PANEL REPAIRED	الارضية
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
06.B Head Light	LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
<b>07 Interior Condition</b>		<b>الحالة الداخليه</b>
07.A AC Condition	OK	المكيف
07.B Power Window Switch	NOT WORKING FROM MAIN SWITCH	مفتاح النافذه
<b>08 Battery Condition</b>		<b>حالة البطارية</b>
08.A Battery bracket	MISSING	حامل البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Change possession :	66436305
Chassis No :	JTHBH96S565026778
Vehicle Make :	LEXUS
Vehicle Model :	GS300
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	347346 Kms.
Origin :	Japan
Model Year :	2006
Gear Type :	Automatic
Engine Size :	5000 CC
Engine No :	NIL
Horse Power :	245
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1600 Kgs. 2000 Kgs.

Certificate Number :	5-TAS-2022-16709723
Inspection Date :	08-05-2022
Certificate Print Date :	08-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	5 min 38 sec
Appointment Ref Number :	--
Start Time :	13:36
End Time :	13:42
Lane :	02
Token No. :	247
Attempt :	1
Prints No :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)



9091 KM

Distance per  
year



936 L

Fuel consumed  
per year



1517 AED

Fuel cost per  
year



2.3 ton

Carbon footprint  
per year

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
9 %	8 %	5 %	0 %

Vehicle on Petrol HC Reading  
0 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5000	3000	

Inspection Remarks: REAR RIGHT SIDE CHASSIS , WHEEL HOUSING , COMPARTMENT REPAIRED //OLD //

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460 71051	Cash	16709723	AED 170 Collected on 08/05/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

