



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 13 Jan 2023, 10:26:32 |
| Transaction Number | 43819477 (CC10009) | Queue Number | 656762 |



| | |
|------------------|--------------------------|
| Chassis Number | 1FA6P8CFXF5413257 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Ford |
| Model | Mustang |
| Model Year | 2015 |
| Color | Black |
| Mileage | 63974 Miles |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | Imported |

| DEFECT | REMARKS | |
|------------------------------|--|----------------------------|
| 01 Body | | جسم المركبة |
| 01.A Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 01.B Fenders | REFITTED | مدكار |
| 01.C Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 01.D Bumper | MISALIGN | دعامية |
| 01.E Bonnet | REFITTED | غطاء المحرك |
| 01.F Vehicle Color | GRAY | لون المركبة |
| 01.G Other | FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED | اخرى |
| 01.H Paint | BODY TOTALY REPAINTED EXCEPT ROOF & PORTION REPAIRED,MINOR DENT SCRATCHES | الصبغ |
| 02 Chassis Condition | | الشاسي |
| 02.A Chassis | FRONT BOTH SIDE CHASSIS REPAIRED SUSPECT REPLACED / | الشاسية |
| 03 Interior Condition | | الحالة الداخليه |
| 03.A Air Bag | LEFT SIDE DAMAGED | وسائد هوائية |
| 03.B Roof Ceiling | LOOSE & PORTION CUT | بطانه السقف |
| 03.C Steering Wheel and | WORN OUT | عجلة القيادة وازرار التحكم |

| DEFECT | REMARKS | |
|------------------------------------|--|--------------------------|
| control buttons | | |
| 03.D AC Condition | OK | المكيف |
| 04 Tires and Rims Condition | | الاطارات |
| 04.A Rear Tyre | BOTH SIDE 2017 CRACKED , EXPIRED | الاطار الخلفي |
| 04.B Spare Tire &Tools | MISSING | الاطار الاحتياطي و العدة |
| 04.C Front Tyre | BOTH SIDE 2017 CRACKED , EXPIRED | الاطار الامامي |
| 05 Suspension System | | ممتص الصدمات |
| 05.A Other | STIBILZER LINK BOOT CUT | اخرى |
| 05.B Ball Joint | BOOT CUT | مفصل كروي |
| 05.C Arms | LOWER ARM BUSHES CUT | ازرع |
| 06 Transmission Condition | | الجير |
| 06.A Visual Gear Box Condition | OIL LEAK REFITTED | حالة الجير النظرى |
| 06.B Road Test | NOT CHECK | فحص علي الطريق |
| 06.C Gear Box Mount | MOUNT RUBBER CUT | كرسي الجير |
| 07 Steering Condition | | المقود |
| 07.A Steering Boot | BOOT CUT | ربلة المقود |
| 07.B Steering Oil | OIL LEAK | زيت المقود |
| 07.C Tie Rod End | BOOT CUT | مؤخرة الرودادت |
| 08 Engine Condition | | المحرك |
| 08.A Mount | MOUNT RUBBER CUT | كرسي |
| 08.B Visual Engine Condition | ENGINE OIL WATER MIXED/OIL LEAK REFITTED | حالة المحرك النظرى |
| 09 Lights | | الاضاءة |
| 09.A Warning Light | WARNING LIGHTS ON IN DISPLAY. | ضوء تحذير |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.