





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20189206	Plate Category	: PRIVATE
Transaction Date	: 09 JUL 2020 15:01:58	Plate Number	: 021875 EA
Queue Number	: 193782	Import Doc. Ref.	:
Chassis Number	: MR2K19F39H1021875	Manufacturer/Model	: TOYOTA/YARIS
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفرامل
13.04 - Brake Test	Passed		فحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
VISUAL TEST:			
01 Lights			الانوار
01.04 - Head Lights		HEAD LIGHT REPLACED/ OTHER MANUFACTURER	الانوار الامامية
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		FRT TIRE 2618/ FRT L/S TIRE SIDE WORN/ NOISY&VIBRATION	الاطارات الامامية
04.04 - Rear Left And Right Hand Tires		RR B/S TIRE 12618	الاطارات الخلفية
05 Body			الهيكل
05.02 - Paint		MINOR BODY DENT&SCRATCHES	الصبغ
05.03 - Doors		RR L/S DOOR&FENDER REPAIRED	الابواب
05.04 - Fenders		FRT L/S FENDER& R/S WHEEL HOUSING&FRAME REPAIRED&FRT R/S FENDER REPLACED	المدكار
05.05 - Bumpers		RR BUMPER MOUNTING HOLDER DAMAGE	الدعامية
05.08 - Chassis (Frame)		FRT R/S CHASSIS DENT	الشاصية
05.09 - Front And Rear Windshields		FRT WIND SHIELD REPLACED OTHER MANUFACTURER	الزجاج الامامي والخلفي
05.12 - Side Safety Frame		FRT BONNET/ B/S FENDER&BULKHEAD&BUMPER REFITTED	الواقيات الجانبية
06 General Items			الاشياء العامة
06.01 - Wiper Blades		WIPER BLADE WORN	ماسحات الزجاج الامامي
06.03 - Wiper Water System		WIPER WASHER WATER TANK REPAIRED	نظام رش ماء ماسحات الزجاج
06.08 - Interior Lights		INTERIOR LIGHT MISSING	الانوار الداخلية
06.12 - Seats Condition And Seats Fixing		INTERIOR COVER PARTLY WORN	المقاعد وحالتها وتثبيتها
07 Remarks			ملاحظات
07.04 - Others		ODO METER 71242	ملاحظات اخرى
09 Auction			الفحص الكامل



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20189206	Plate Category	: PRIVATE
Transaction Date	: 09 JUL 2020 15:01:58	Plate Number	: 021875 EA
Queue Number	: 193782	Import Doc. Ref.	:
Chassis Number	: MR2K19F39H1021875	Manufacturer/Model	: TOYOTA/YARIS
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident	RR L/S REPAIRED	أثر حادث في جوانب المركبة
09.25 - Body Repainted	BODY PORTION REPAINTED	أثر صنيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		

Test Certificate

PASS



Plate Details :	--
Chassis No :	MR2K19F39H1021875
Vehicle Make :	TOYOTA
Vehicle Model :	YARIS
Vehicle Class :	Light Vehicle
Body Type :	HATCHBACK
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	71243 Kms.
Origin : Thailand	Model Year : 2017
Gear Type : --	Engine No : 5092988
Engine No : 5092988	Engine Size : 1500 CC
Axles No : 2	Horse Power : 107
No Of Doors : 4	Cylinders : 4
G. V. W. : 1500 Kgs.	No Of Seats : 5
	Empty Weight : 1151 Kgs.

Certificate Number :	5-TAS-2020-12141531
Inspection Date :	12-07-2020
Certificate Print Date :	12-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	7 min 52 sec
Appointment Ref Number :	--
Start Time :	End Time :
12:40	12:48
Lane :	Token No. :
01	5
Attempt :	Prints No. :
1	1

Carbon footprint



0.1 ton



12+

ton CO2

Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



185 KM

Distance per year



11 L

Fuel consumed per year



18 AED

Fuel cost per year



0.1 ton

Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle
7 %

Service brake imbalance on rear axle
2 %

Parking brake imbalance between LHS and RHS
1 %

Vehicle on Petrol CO Reading
0 %

Vehicle on Petrol HC Reading
15 PPM VOL

Inspection Remarks: FRONT RIGHT SIDE MEMBER END MINOR DENT & SLIGHT BEND/BULKHEAD FENDER & BUMPER FRAME REPAIRED

Payment Details

Inspection Performed by
62424

Parking Slot No
--

Payment Method
VTP Credit Account

Service Name
Registration Test

Transaction Number
12141531

Attempt
1

Service Fees
AED 170 Collected on 12/07/2020

Received by
Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

