



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 Nov 2022, 14:59:09
Transaction Number	34774682 (CC10010)	Queue Number	616927



Chassis Number	1V2MR2CA3JC502135
Engine Number	
Vehicle Class	Car
Manufacturer	Volkswagen
Model	
Model Year	2018
Color	White
Mileage	140885 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Sign of front accident		وجود مؤشر لحادث في المقدمة
01.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
01.C Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER APRON ,WHEEL ARCH REPAIRED.	اخرى
01.D Fenders	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED & REFITTED	مدكار
01.E Doors	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED	أبواب
01.F Bonnet	PORTION REPAIRED,REPAINTED & REFITTED	غطاء المحرك
01.G Bumper	REAR,BUMPER BRACKET ,BACK PANEL DENT .	دعامية
01.H Vehicle Model	ATLAS	طراز المركبة
01.I Sign of back accident		وجود مؤشر لحادث في الخلف
01.J Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .SIGN OF FLOODED.	صدأ
01.K Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.L Floor	RIGHT SIDE UNDER COVER MISSING ,LEFT SIDE COVER PORTION DAMAGED ,CHECKED ONLY VISIBLE AREA .	الارضية

DEFECT	REMARKS	
02 Chassis Condition		الشاسي
02.A Chassis Number	VIN AREA DENT .	رقم القاعدة
02.B Chassis	FRONT RIGHT SIDE CHASSIS BEND.	الشاسيه
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020/2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
04 Interior Condition		الحاله الداخليه
04.A AC Condition	OK	المكيف
04.B Mirror	LEFT SIDE NOT WORKING	المرايا
04.C Roof Ceiling	PORIOTN LOOSE	بطانه السقف
04.D Air Bag	DAMAGED	وسائد هوائية
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	OIL SUMP DENT .	حالة الجير النظري
06 Steering Condition		المقود
06.A Tie Rod End	BALL JOINT BOOT CUT.	مؤخرة الرودادت
07 Suspension System		ممتص الصدمات
07.A Suspension Subframe	REFITTED ,PORTION DENT .	
08 Brake Condition		الفرامل
08.A Other	FRONT RIGHT SIDE BRACKET DENT.	اخرى
09 Exhaust System		نظام العادم
09.A Other	REFITTED.	اخرى
10 Lights		الاضاءة
10.A Warning Light	WARNING MESSAGE ON IN CLUSTER.	ضوء تحذير
11 Engine Condition		المحرك
11.A Visual Engine Condition	PARTS GETTING RUSTY ..	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	1V2MR2CA3JC502135
Vehicle Make :	VOLKSWAGEN
Vehicle Model :	ATLAS
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	226756 Kms.
Origin : United States	Model Year : 2018
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : nil	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 7
G. V. W. : 2600 Kgs.	Empty 2200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18063880		
Inspection Date :	09-11-2022		
Certificate Print Date :	09-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	2 min 30 sec		
Appointment Ref Number :	--		
Start Time :	22:32	End Time :	22:34
Lane :	02	Token No. :	287
Attempt :	2	Prints No. :	1

Carbon footprint



Take action to protect Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

32393 KM	3334 L	11369 AED	8.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks:

FRONT RIGHT SIDE CHASSIS END MINOR DENT/ FRONT BULKHEAD/ FRONT RIGHT SIDE FENDER&FRAME&WHEEL HOUSING REPAIRED

Payment Details

Inspection Performed by 3104	Payment Method Cash	Transaction Number 18063880	Service Fees AED 70 Collected on 09/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

