

Queue Number 2836720

Transaction Date 05 Oct 2026, 17:06:02

Site Name
840 - Emirates AuctionsTransaction Number
51064157 (CC10013) (CC10011)

Vehicle Details

Chassis Number	1GCHC24U96*****
Specification	Imported
Make	Chevrolet
Model	Silverado
Model Year	2006
Color	Green
Mileage	152499 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED REPAIRED, MINOR DENT SCRATCHES, PORTION GETTING RUSTY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK PORTION RUSTY DAMAGED	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Bonnet	GRILL LOGO FADED PORTION CRACK	غطاء المحرك
01.F Pillars	BOTH SIDE B/PILLAR OUTAR PANEL REPAIRED	القوائم
01.G Trunk	TAIL GATE ,CARRIOR BOX UPPER STRIP, LOCK HANDLE COVER MISSING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME RUST PROOFED GETTING RUSTY / REAR CROSS MEMBER RUSTY HOLE WEAK	الشاسيه
02.B Chassis Number	DOOR POST STICKER FADED / VIN CHECK GLOVE BOX & WINDSHIELD STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER	حالة المقاعد
---------------------	-------------	--------------

05 Exhaust System

نظام العادم

Condition	Remarks	الحالة
05.A Other	GETTING RUSTY	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	EXTRA STICKER	الاضاءة الرئيسية
08.B Tail Light	PORTION CRACKED	الضوء الخلفي
08.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	ازرع
09.B Arms	ARM BUSHES DRY CRACK	
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY (SIGN OF FLOODED)	اخرى
10.B Mirror	CENTER VIEW MIRROR FADED	المرآيا
10.C AC Condition	OK	المكيف
10.D Dash Board	PORTION WORN OUT	لوحة القيادة
10.E Roof Ceiling	REFITTED PORTION LOOSE	بطانة السقف
10.F Door Panel	PORTION GETTING WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

