



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 May 2022, 10:35:02**
 Transaction Number **82104244 (CC10008)** Queue Number **312309**



Chassis Number **JTEHT05J412013931**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Land Cruiser**
 Model Year **2001**
 Color **White**
 Mileage **174225 Miles**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **USA Imported**

DEFECT	REMARKS	
01 Body جسم المركبة		
01.A Paint	BODY PORTION REPAIRED, REPAINTED, MINOR DENT, SCRATCHES, PORTION RUSTY	الصبغ
01.B Fenders	PORTION REPAIRED, REPAINTED	مدكار
01.C Doors	PORTION REPAINTED, PORTION REPAIRED & LEFT SIDE DOOR MISALIGN	أبواب
01.D Bonnet	PORTION REPAIRED, REPAINTED	غطاء المحرك
01.E Trunk	PORTION REPAIRED, REPAINTED	صندوق
02 Interior Condition الحالة الداخلية		
02.A Other	CENTER CONSOLE BOX LOCK DAMAGED	اخرى
02.B Power Window Switch	MAIN SWITCH LOOSE	مفتاح النافذه
02.C Mirror	VIEW MIRROR LOOSE	المرآيا
02.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.E AC Condition	OK	المكيف
03 Transmission Condition الجير		
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box	REFITTED	حالة الجير النظري

DEFECT	REMARKS	
Condition		
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020 & MINOR WORN OUT	الاطار الخلفي
04.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
04.D Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
05 Chassis Condition		الشاسي
05.A Chassis	REAR BOTH SIDE CHASSIS ARCH BULGDE	الشاسيه
06 Suspension System		ممتص الصدمات
06.A Arms	FRONT LOWER ARM BUSHES &CONTROL BUSHES CRACKED	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
07 Seats Condition		المقاعد
07.A Seat Condition	SEATS HAVE EXTRA COVER & REAR SEAT MISSING	حالة المقاعد
08 Lights		الاضاءة
08.A Head Light	BOTH SIDE BRACKET BROKEN & FIXED BY WIRES	الاضاءة الرئيسية
08.B Indicator & Hazard light	FRONT RIGHT SIDE INDICATOR LIGHT LOOSE	الاشارات
09 Engine Condition		المحرك
09.A Visual Engine Condition	REFITTED	حالة المحرك النظري
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10.B Steering Boot	BOOT CUT	ربلة المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✗ FAILED

Plate Details : A 15505 Umm Al Quwain Private

Chassis No : JTEHT05J412013931

Vehicle Make : TOYOTA

Vehicle Model : LAND CRUISER

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : White

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 174225 Kms.

Origin : Japan

Model Year : 2001

Gear Type : Automatic

Engine Size : 5700 CC

Engine No : NONE

Horse Power : 290

Axles No : 2

Cylinders : 8

No Of Doors : 5

No Of Seats : 8

G. V. W. :

2713 Kgs.

Empty Weight : 1815 Kgs.

Certificate Number : 5-TAS-2022-16842512

Inspection Date : 25-05-2022

Certificate Print Date : 25-05-2022

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Al Aweer

Total Time Taken :
21 min 31 sec

Appointment Ref Number : --

Start Time : 11:04

End Time : 11:26

Lane : 02

Token No. : 132

Attempt : 1

Prints No : 1

Parameter Readings

Service brake imbalance on
front axle

1 %

Service brake imbalance on
rear axle

3 %

Parking brake imbalance
between LHS and RHS

14 %

Vehicle on Petrol CO
Reading

0 %

Vehicle on Petrol HC
Reading
6 PPM VOL

Inspection Findings

Defects

Front Registration plate

FIX BOTH SIDE NUMBER PLATE PROPERLY

Issue

Improper position

Severity

Major

Spare Tire

KEEP SPARE TIRE

Missing (Major)

Major

Discrepancies

Engine Size Discrepancy in Engine Size

Old Value

5700

New Value

4700

Verified

Inspection Remarks: UNDERNEATH COMPONENTS MINOR RUSTY

Payment Details

Inspection Performed by

34439

Payment Method

VTP Credit Account

Transaction Number

16842512

Service Fees

AED 170 Collected on 25/05/2022

Parking Slot No

--

Service Name

Registration Test

Attempt

1

Received by

Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

