



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Mar 2023, 13:03:00
Transaction Number	22576717 (CC10010)	Queue Number	686744



Chassis Number	JTJHY00W7G4191531
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LX 570
Model Year	2016
Color	White
Mileage	240397 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	REFITTED ,SIGN OF OIL WET.	حالة الجير النظرى
02 Tires and Rims Condition		الاطارات
02.A Rear Tyre	BOTH SIDE 2019,	الاطار الخلفي
02.B Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
02.C Front Tyre	BOTH SIDE 2019,	الاطار الامامي
03 Body		جسم المركبة
03.A Floor	UNDER FLOOR PORTION MUDDY	الارضية
03.B Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
03.C Doors	REFITTED	أبواب
03.D Sign of side accident		وجود مؤشر لحادث في الجانب
03.E Sign of front accident		وجود مؤشر لحادث في المقدمة
03.F Bonnet	REFITTED	غطاء المحرك
03.G Fenders	REFITTED	مدكار

DEFECT	REMARKS	
03.H Pillars	BOTH IDE PILLAR DOOR POST REPAIRED REPAINTED , FOR RECHECK PROEPRLY REMOVE COVERS & BEDDING	القوائم
03.I Roof	BOTH SIDE ROOFRAILL REPAIRED REPAINTED	السدق
03.J Paint	BODY REPAINTED PORTION ,REPAIRED & MINOR DENT SCRATCHES,	الصبغ
04 Interior Condition		الحاله الداخليه
04.A AC Condition	OK	المكيف
04.B Roof Ceiling	PORTION LOOSE	بطانه السقف
04.C Door Panel	REAR RIGHT SIDE HOLDER COVER MISSING.	لوحة بطانة الباب
04.D Steering Wheel and control buttons	STEERING WHEEL NOT CENTER.	عجلة القيادة وازرار التحكم
04.E Power Window Switch	REAR RIGHT SIDE NOT WORKING ON MAIN SWITCH.	مفتاح النافذه
05 Chassis Condition		الشاسي
05.A Chassis	FRONT BOTH SIDE CHASSIS CROSS MEMBER REPAIRED ,RIGHT SIDE CHASSIS BEND	الشاسيه
05.B Chassis Number	VIN PUNCHING NUMBER AREA REPAIRED	رقم القاعده
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT & WARNING MESSAGE ON DISPLAY.	ضوء تحذير
08 Engine Condition		المحرك
08.A Visual Engine Condition	REFITTED	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	JTJHY00W7G4191531
Vehicle Make :	LEXUS
Vehicle Model :	LX 570
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White, Pearl
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	240396 Kms.
Origin : Japan	Model Year : 2016
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : 3257783	Horse 388
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 8
G. V. W. : 2500 Kgs.	Empty 1620 Kgs.
	Weight :

Certificate Number :	5-TAS-2023-18940060		
Inspection Date :	04-03-2023		
Certificate Print Date :	04-03-2023		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Qusais		
Total Time Taken :	8 min 11 sec		
Appointment Ref Number :	--		
Start Time :	9:49	End Time :	9:57
Lane :	03	Token No. :	154
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

24 KM	3 L	11 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on rear axle 2 %	Service brake imbalance on front axle 4 %	Parking brake imbalance between LHS and RHS 4 %	Vehicle on Petrol CO Reading 0.02 %
Vehicle on Petrol HC Reading 1 PPM VOL			

Inspection Remarks:

Front bumper, bulk head, fender, fender frame repaired, right side A pillar repaired. Front right side chassis and cross member repaired. OK BY CCM W/O#2023-03-04-1.Fix right side running board cover and foot board as soon as possible

Payment Details

Inspection Performed by 2337 22145 22145	Payment Method Cash	Transaction Number 18940060	Service Fees AED 170 Collected on 04/03/2023
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Mohammed Ahmed Mohsen Albaidhani

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفتي للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.



