



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jun 2022, 12:51:09
Transaction Number	12644939 (CC10006)	Queue Number	312309



Chassis Number	JN8AZ1MW8BW160985
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Murano
Model Year	2011
Color	White
Mileage	144880 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED,REFITTED & REAR RIGHT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Other	FROTN BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.E Doors	FRONT RIGHT SIDE REPAINTED & REAR RIGHT SIDE REPAIRED,REPAINTED	أبواب
01.F Rusty	UNDER FLOOR FLOOR PARTS CHASSIS GETTING RUSTY	صدأ
01.G Bumper	MISALIGN , REAR BUMPER ALUMUNIUM COVER DAMAGED	دعامية
02 Lights		الاضاءة
02.A Warning Light	WARNING LIGHTS ON IN DISPLAY	ضوء تحذير
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري

DEFECT	REMARKS	
03.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019, CRACKED , WORN OUT	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2016 CRACKED , EXPIRED	الاطار الخلفي
04.C Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
05 Suspension System		ممتص الصدمات
05.A Shock Absorber	REAR LEAK	ممتص الصدمات
05.B Other	STABLIZER LINK BOOT CUT	اخرى
05.C Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
05.D Ball Joint	BOOT CUT	مفصل كروي
06 Chassis Condition		الشاسي
06.A Chassis Extension	REAR BOTH SIDE CHASSIS EXTENSION RUSTY	تمديدات الشاسي
06.B Chassis	FRONT LEFT SIDE CHASSIS OUTER MINOR DETACHED & DENT	الشاسيه
07 Steering Condition		المقود
07.A Axle	LEAK	اكسلات
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.C Other	STEERING HARD	اخرى
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK	المكيف
08.B Air Bag	LEFT AIR BAG DAMAGED ,MISSING	وسائد هوائية
08.C Mirror	VIEW MIRROR LOOSE	المرايا
09 Engine Condition		المحرك
09.A Visual Engine Condition	MINOR OIL, LEAK	حالة المحرك النظري
09.B Mount	MOUNT RUBBER CRACKED	كرسي
09.C Smoke	WHITE SMOKE	دخان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	JN8AZ1MW8BW160985
Vehicle Make :	NISSAN
Vehicle Model :	MURANO
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	144880 Kms.
Origin : Japan	Model Year : 2011
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : NIL	Horse 260
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2722 Kgs.	Empty 1795 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17079695		
Inspection Date :	26-06-2022		
Certificate Print Date :	26-06-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 41 sec		
Appointment Ref Number :	--		
Start Time :	13:40	End Time :	13:51
Lane :	01	Token No. :	197
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

10348 KM	1065 L	1726 AED	2.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 2 %	Service brake imbalance on rear axle 13 %	Parking brake imbalance between LHS and RHS 11 %	Vehicle on Petrol CO Reading 0.05 %
Vehicle on Petrol HC Reading 4 PPM VOL			

Inspection Remarks: FRONT RIGHT SIDE FENDE,FRONT BUMPER REPAIRED,BODY MINOR SCRATCHES

Payment Details

Inspection Performed by 62439 25101	Payment Method Cash	Transaction Number 17079695	Service Fees AED 170 Collected on 26/06/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
 - Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
- تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.