



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Jan 2023, 17:01:03</b>
Transaction Number	<b>67019553 (CC10006)</b>	Queue Number	<b>657751</b>



Chassis Number	<b>JMYSTCS3A7U012865</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Lancer</b>
Model Year	<b>2007</b>
Color	<b>Silver</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT CHECK,GRILL PORTION DAMAGED	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C Odometer reading	NOT CHECK	قراءة عداد المسافات
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Sign of back accident		وجود مؤشر لحادث في الخلف
02.B Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
02.C Other	REAR BACK PANEL,QUATER PANEL,WHEEL ARCH REPAIRED	اخرى
02.D Bumper	MISALIGN	دعامية
02.E Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
02.F Trunk	SPOILAR PORTION DAMAGED	صندوق
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Axle	BOOT CUT	اكسلات
03.B Steering Oil	OIL LEAK	زيت المقود
03.C Steering Boot	BOOT CUT	ربلة المقود

DEFECT	REMARKS	
03.D Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2018 & CRACKED,EXPIRED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018 & CRACKED,EXPIRED	الاطار الخلفي
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Other	STABILIZER LINK BOOT CUT	اخرى
05.B Arms	LOWER ARM BUSH CRACKED	ازرع
05.C Ball Joint	BOOT CUT	مفصل كروي
05.D Shock Absorber	LEAK	ممتص الصدمات
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	LENS FADED,ALL LIGHT NOT CHECK,LEFT SIDE MISALIGN	الاضاءة الرئيسية
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	NOT CHECK,OIL LEAK	حالة الجير النظري
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION END REPAIRED	الشاسيه
08.B Chassis Number	VIN NUMBER CHECK ONLY APRON AREA	رقم القاعدة
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.