

01.I Floor

03 Wipers and Arms

TEST CERTIFICATE

Site Number 840-Emirates Auctions

Transaction Number **83804992 (CC10006)**

Transaction Date

21 Dec 2021, 17:54:10

WDDDJ5EB4AA162267

Queue Number 312309

Chassis Number

Engine Number

Vehicle Class

Car

Manufacturer

Mercedes

Model

CLS 300

Model Year

2010

Color

White

Mileage

254872 Km

Fuel Type

Petrol

No. Of Cylinders

_

Specification

GCC Specification

الارضية

المساحات

DEFECT REMARKS

01 Body	مركبة	ىم الد	جس	J
---------	-------	--------	----	---

01.A Fenders	FRONT BOTH SIDE REPAINTED	مدكار
01.B Bonnet	REPAINTED & LOGO MISSING	غطاء المحرك
01.C Trunk	REPAIRED, REPAINTED & INNER COVER HANDLE MISSING	صندوق
01.D Bumper	REPAINTED	دعامية
01.E Doors	FRONT LEFT SIDE REPAINTED	أبواب
01.F Paint	PORTION REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.G Pillars	LEFT SIDE INNER COVER PORTION DAMAGED	القوائم
01.H Door Handle &Lock	OUTER LOCK BUTTON MISSING	مقابض الأبواب والأقفال

O2 Interior Condition الحاله الداخلية

REAR RIGHT SIDE RUNNING BOARD COVER SPOT HOLE

02.A Mirror	RIGHT SIDE MISSING	المرايا
02.B Sunroof	CARTAIN DAMAGED & SLYDING NOT WORK PROPERLY	فتحت سقف
02.C Roof Ceiling	REAR LOOSE	بطانه السقف
02.D AC Condition	NOT COOLING	المكيف
02.E Other	REAR GLASS STAND NOT WORKING	اخري

DEFECT	REMARKS	
03.A Wiper Arm &Blade	BOTH SIDE BLADE MISSING	ازرع المساحات والشفرات
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04.B Head Light	OK & RIGHT SIDE WASHER COVER MISSING	الاضاءة الرئيسية
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06 Engine Condition		المحرك
06.A Engine Condition	OIL LEAK	حالة المحرك
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	ОК	الجير
07.C Propeller Shaft	RUBBER CRACKED	ناقل الحركة
08 Chassis Condition		الشاصي
08.A Chassis	VISABLE AREA OK	الشاسيه
09 Seats Condition		المقاعد
09.A Seat Condition	ОК	حالة المقاعد
10 Steering Condition		المقود
10.A Rack Pinion	OIL LEAK	مسطرة المقود
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.