

Queue Number 2688857

Transaction Date 27 Aug 2026, 16:12:52

Site Name
840 - Emirates AuctionsTransaction Number
11051082 (CC10021) (CC10011)

Vehicle Details

Chassis Number KNAFW6124D*****
 Specification Imported
 Make Kia
 Model Cerato
 Model Year 2013
 Color Red
 Mileage 229664 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED FRONT REFITTED,REAR RIGHT PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED	الصبغ
01.C Doors	LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN,PORTION DAMAGED MODIFIED	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED,REFITTED,REAR HANDLE DAMAGED CABLE MODIFIED	غطاء المحرك
01.G Pillars	LEFT SIDE B/PILLAR ROCKER PANEL REPAIRED	القوائم
01.H Trunk	PORTION REPAIRED REPAINTED REFITTED,EXTRA MODIFIED SPOILER,SPARE WHEEL HOUS COVER MISSING	صندوق
01.I Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY,SHAKING,COMPARTMENT PARTS SIGN OF BURNING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Belt	FRONT RIGHT SIDE NOT WORKING,LEFT SIDE PORTION BURN DAMAGED BRACKET COVER MISSING	حزام الأمان
04.B Seat Condition	EXTRA COVER PORTION DAMAGED , DRIVER SEAT SIDE COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LENS FADED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION LOOSE	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	RIGHT SIDE LOOSE	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX PORTION LOOSE , INTERIOR PARTS RUSTY SIGN OF WATER FLOODED(INTERIOR SIGN OF BURNING PARTS REFITTED)	اخرى
10.B AC Condition	OK , GRILL PORTION DAMAGED	المكيف
10.C Dash Board	PORTION DAMAGED	لوحة القيادة
10.D Roof Ceiling	REPLACED PORTION LOOSE	بطانه السقف
10.E Sun Visor	BOTH EXTRA COVER	حاجب الشمس
10.F Odometer reading	CLUSTER COVER PORTION FADED	قراءة عداد المسافات
10.G Door Panel	WORN OUT	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT , HORN NOT WORKING	عجلة القيادة وازرار التحكم
10.I Sunroof	CURTAIN LOOSE	فتحت سقف
10.J Gear Shifting Lever	KNOB WORN OUT , LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae