



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 Jan 2022, 18:19:33
Transaction Number	60137034 (CC10006)	Queue Number	312309



Chassis Number	1D4SE4GT9BC704588
Engine Number	
Vehicle Class	Car
Manufacturer	Dodge
Model	Durango
Model Year	2011
Color	Silver
Mileage	164264 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	FRONT & REAR BOTH SIDE REPAINTED & FRONT RIGHT SIDE PORTION REPAIRED,REAR RIGHT SIDE REFITTED	أبواب
01.B Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.C Bumper	REPAINTED,SCRATCHES,MISALIGN	دعامية
01.D Fenders	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.E Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,	الصبغ
01.F Trunk	REPAINTED,PORTION REPAIRED	صندوق
02 Lights		الاضاءة
02.A Indicator & Hazard light	REAR RIGHT SIDE INDICATOR NOT WORKING	الاشارات
02.B Head Light	RIGHT SIDE LIGHT LOOSE	الاضاءة الرئيسية
02.C Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02.D Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
02.E Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
02.F Tail Light	REAR RIGHT SIDE PARK LIGHT NOT WORKING	الادارة
03 Interior Condition		الحاله الداخليه

DEFECT	REMARKS	
03.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.B AC Condition	OK & REAR LEFT SIDE GRILL ADJUSTMENT BUTTON MISSING	المكيف
03.C Other	HAND REST LEATHER CRACKED	اخرى
03.D Sun Visor	RIGHT SIDE GLASS COVER MISSING	حاجب الشمس
04 Engine Condition		المحرك
04.A Engine Condition	REFITTED , SHAKING	حالة المحرك
05 Transmission Condition		الجير
05.A Gear Box	MINOR OIL LEAK&REFITTED	الجير
05.B Propeller Shaft	FRONT PROPELLER SHAFT MISSING	ناقل الحركة
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Exhaust System		نظام العادم
06.A Modification	CATAYLIC CONVERTER OPEN ,REWELDED	تعديلات
07 Steering Condition		المقود
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.C Axel	FRONT LEFT INNER AXLE BOOT GREASE LEAK	اكسلات
08 Suspension System		ممتص الصدمات
08.A Arms	FRONT LOWER ARM BUSHED CRACKED	ازرع
09 Seats Condition		المقاعد
09.A Seat Belt	OK	حزام الأمان
09.B Seat Condition	FRONT LEFT SIDE MINOR DAMAGED	حالة المقاعد
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
10.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES & FRONT LEFT SIDE & REAR RIGHT SIDE WHEEL HUB COVER MISSING	حالة الجنوط
11 Wipers and Arms		المساحات
11.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
12 Chassis Condition		الشاسي
12.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.



- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.