



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>03 Jul 2022, 15:46:45</b>
Transaction Number	<b>77107719 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JMYMYV87WFJ719819</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Pajero</b>
Model Year	<b>2015</b>
Color	<b>Brown</b>
Mileage	<b>115487 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
01.C Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Shock Absorber	FRONT SHOCK ABSORBER LEAK	ممتص الصدمات
03.B Ball Joint	BOOT CUT	مفصل كروي
03.C Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK & GRILL LOOSE	المكيف
04.B Mirror	LEFT SIDE FOLDING NOT WORKING & ADJUSTMENT NOT WORKING PROPERLY	المرايا
<b>05 Body</b>		<b>جسم المركبة</b>

DEFECT	REMARKS	
05.A Paint	REPAINTED,PORZION REPAIRED,BODY MINOR DENT,SCRATCHES	الصبغ
05.B Fenders	FRONT FENDER REFITTED	مدكار
05.C Bonnet	REFITTED	غطاء المحرك
05.D Sign of front accident		وجود مؤشر لحادث في المقدمة
05.E Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Fog light	NOT WORKING	كشاف الضباب
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Mount	MOUNT BUSH CRACKED	كرسي
07.B Visual Engine Condition	SIGN OF MINOR OIL LEAK , REFITTED	حالة المحرك النظرى
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	R 32837 Dubai Private
Chassis No :	JMYMYV87WFJ719819
Vehicle Make :	MITSUBISHI
Vehicle Model :	PAJERO
Vehicle Class :	Light Vehicle
Body Type :	JEEP
Fuel :	Benzene
Color :	Brown
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	115496 Kms.
Origin : Japan	Model Year : 2015
Gear Type : Automatic	Engine Size : 3800 CC
Engine No : 6G75YG5464	Horse : --
Axles No : 2	Power :
No Of : 2	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2450 Kgs.	Empty Weight : 1995 Kgs.

**Retest can be done only in Dubai**

Certificate Number :	5-TAS-2022-17234721		
Inspection Date :	19-07-2022		
Certificate Print Date :	19-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 54 sec		
Appointment Ref Number :	--		
Start Time :	17:53	End Time :	18:04
Lane :	03	Token No. :	232
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	2 %	1 %	0 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Engine replace left& right mounting	Worn out rubber mountings	Major
Engine	Oil leaking continuously	Major
Gear/Differential replace transmission mounting	Worn out rubber mountings (Major)	Major

**Inspection Remarks:** Front both side chassis repaired/have ccm,bulk head,bumper frame,fender,fender frame repaired

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
35063	VTP Credit Account	17234721	AED 170 Collected on 19/07/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

- i** This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- i** Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
- تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

