

Condition

TEST CERTIFICATE

Site Number 840-Emirates Auctions Transaction Date 04 Dec 2022, 17:34:40

Transaction Number 14724347 (CC10010) Queue Number 635608



Chassis Number JTEBU25J985148569

Engine Number

Vehicle Class Car

Manufacturer **Toyota**

Model Prado

Model Year 2008

Color White

Mileage **01 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT	REMARKS

01 Tires and Rims Condition		الاطارات
01.A Rear Tyre	BOTH SIDE 2006/2018 EXPIRED ,CRACKED .	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2016/2018 EXPIRED ,CRACKED .	الاطار الامامي
02 Suspension System		ممتص الصدمات
02.A Shock Absorber	LEAK & FRONT LEFT SIDE MOUNT BOLT MISSING	ممتص الصدمات
02.B Other	STABILIZER LINK BOOT CUT	اخري
02.C Arms	LOWER ARM BUSH CUT	ازرع
03 Lights		الاضاءة
03.A Head Light	FADED & LIGHTING SYSTEM NOT CHECKED.	الاضاءة الرئيسية
03.B Indicator & Hazard light	LEFT SIDE FENDER SIDE MISSING.	الاشارات
04 Exhaust System		نظام العادم
04.A Other	MOUNTING BUSHES REMOVED .MISSING .	اخري
05 Transmission Condition		الجير
05.A Gear Box Mount	MOUNT WEAK	كرسي الجير
05.B Visual Gear Box	NOT CHECKED . OIL LEAK, REFITTED	حالة الجير النظرى

DEFECT	REMARKS	
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,IGINITION NOT WORKING.OIL LEAK,REFITTED	حالة المحرك النظرى
06.B Mount	MOUNT WEAK	كرسي
07 Body		جسم المركبة
07.A Bonnet	REFITTED,STAY SHOCK WEAK .	غطاء المحرك
07.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
07.C Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,REPAIRED.	اخري
07.D Fenders	REFITTED .	مدكار
07.E Fuel Tank	COVER DENT	خزان الوقود
07.F Bumper	MISALIGN.	دعامية
07.G Paint	PORTION REPAIRED ,REPASINTED ,PORTION FADED ,PORTION RUSTY .	الصبغ
07.H Sign of front accident		وجود مؤشر لحادث في المقدمة
08 Chassis Condition		الشاصي
08.A Chassis	FRONT BOTH SIDE CHASSIS SECOND BODY MOUNT BRACKET BADLY RUSTY HOLE WEAK,CHASSIS FRAME RUSTY	الشاسيه
09 Interior Condition		الحاله الداخليه
09.A AC Condition	NOT CHECKED ,AIR VENT ,MISSING ,PORTION DAMAGED .	المكيف
09.B Dash Board	PORTION DAMAGED ,CENTER CONSOLE DAMAGED ,GLOW BOX ,MISSING .	لوحة القياده
09.C Door Panel	PORTION LOOSE.	لوحة بطانة الباب
09.D Odometer reading	NOT WORKING ,NOT CHECKED .	قراءة عداد المسافات
09.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10 Seats Condition		المقاعد
10.A Seat Condition	POTION DAMAGED.	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا
 تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من