



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>12 Jan 2022, 17:52:37</b>
Transaction Number	<b>77322417 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>5TFBV54138X069651</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Toyota</b>
Model	<b>Tundra</b>
Model Year	<b>2008</b>
Color	<b>Antique white</b>
Mileage	<b>20211 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Doors	PORTION REPAIRED , REPAINTED & RIGHT SIDE DEEP DENT	أبواب
01.B Roof	PORTION DENT	السقف
01.C Bumper	REPAINTED	دعامية
01.D Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.E Paint	TOTALY REPAINTED ,PORTION REPAIRED, EXCEPT ROOF & DENTS , SCRATCHES ON BODY	الصبغ
01.F Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.G Floor	REAR CARRIOR BOX PORTION REPAIRED & REPAINTED	الارضية
01.H Trunk	HANDLE LOCK MISSING	صندوق
01.I Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING RUSTY	صدأ
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Head Light	OK	الاضاءة الرئيسية
02.B Indicator & Hazard light	FRONT BOTH SIDE NOT WORKING	الاشارات
02.C Fog light	NOT WORKING	كشاف الضباب
02.D Brake Light	RIGHT SIDE COVER PORTION CRACKED	نور الفرامل
02.E Revers Light	LEFT SIDE COVER PORTION CRACKED	نور الرجوع للخلف

DEFECT	REMARKS	
<b>03 Chassis Condition</b> الشاشي		
03.A Chassis	OK	الشاسيه
<b>04 Engine Condition</b> المحرك		
04.A Engine Condition	OIL LEAK & REFITTED	حالة المحرك
04.B Mount	BUSHES CRACKED	كرسي
<b>05 Transmission Condition</b> الجير		
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Gear Box	OIL LEAK & REFITTED	الجير
<b>06 Seats Condition</b> المقاعد		
06.A Seat Condition	OK	حالة المقاعد
<b>07 Suspension System</b> ممتص الصدمات		
07.A Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
07.B Ball Joint	BUSHES CUT	مفصل كروي
07.C Arms	FRONT LOWER ARM BUSHES CRACKED & ARM RUSTY	ازرع
<b>08 Steering Condition</b> المقود		
08.A Other	STABILIZER LINK BUSHES DRY CRACKED	اخرى
<b>09 Interior Condition</b> الحالة الداخليه		
09.A Mirror	OK	المرايا
09.B Other	CENTER LIGHT COVER MISSING	اخرى
09.C AC Condition	NOT COOLING	المكيف
<b>10 Tires and Rims Condition</b> الاطارات		
10.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.