



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **12 May 2022, 18:04:20**
 Transaction Number **14978899 (CC10008)** Queue Number **312309**



Chassis Number **JTHBG96S765022783**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Lexus**
 Model **GS 300**
 Model Year **2006**
 Color **White**
 Mileage **150830 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE ,REAR LEFT SIDE REPAINTED & REPAIRED & REAR RIGHT SIDE REPAINTED	مدكار
01.B Bonnet	PORTION REPAIRED, REPAINTED & REFITTED	غطاء المحرك
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Pillars	RIGHT SIDE PILLAR REPAINTED, REPAIRED	القوائم
01.E Windshield	REAR CURTAIN NOT WORKING	زجاج
01.F Bumper	MISALIGN	دعامية
01.G Other	FROTN BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.H Paint	BODY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
02 Lights		الاضاءة
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03 Interior Condition		الحالة الداخليه
03.A AC Condition	OK, AIR GRIL PORTION DAMAGED	المكيف
03.B Other	LEFT SIDE FOLDING BUTTON BOX NOT OPEN PROPERLY	اخرى

DEFECT	REMARKS	
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظري
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Arms	LOWER ARM BUSHES MINOR CRACKED	ازرع
07 Chassis Condition		الشاصي
07.A Chassis	FRONT RIGHT SIDE CHASSIS END DENT	الشاسيه
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08.B Other	STABILIZER LINK BOOT CUT	اخرى
09 Seats Condition		المقاعد
09.A Seat Condition	SEAT REAR PORTION CUT	حالة المقاعد
10 Engine Condition		المحرك
10.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
10.B Smoke	BLACK SMOKE	دخان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	JTHBG96S765022783
Vehicle Make :	LEXUS
Vehicle Model :	GS300
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	150833 Kms. x
Origin :	Japan
Model Year :	2006
Gear Type :	Automatic
Engine Size :	5000 CC
Engine No :	3GR0130151
Horse Power :	347
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1455 Kgs. 2000 Kgs.

Certificate Number :	5-TAS-2022-16779976
Inspection Date :	18-05-2022
Certificate Print Date :	18-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	10 min 54 sec
Appointment Ref Number :	--
Start Time :	9:05
End Time :	9:16
Lane :	03
Token No. :	109
Attempt :	1
Prints No. :	1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)

129285 KM	13303 L	21551 AED	31.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
16 %	23 %	21 %	0.46 %

Vehicle on Petrol HC

Reading
208 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Cylinders Incorrect number of cylinders	8	6	
Engine Size Discrepancy in Engine Size	5000	3000	

Inspection Remarks: bulkhead/radiator support repaired /front right side frame member end inner side dent



Odometer Record

Replace Events Date

11/04/2022

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460	Cash	16779976	AED 170 Collected on 18/05/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

