

### **TEST CERTIFICATE**

Site Number
Transaction Number

840-Emirates Auctions 61421057 (CC10006) Transaction Date

10 Aug 2022, 13:16:47

Queue Number 312309

Chassis Number

1ZVBP8AN6A5163248

Engine Number

Vehicle Class

Manufacturer

Model Mustang

Model Year 2010
Color Red

Mileage

109947 Miles

Fuel Type

Petrol

Car

**Ford** 

No. Of Cylinders
Specification

**USA** Imported

**DEFECT** REMARKS

01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
01.B Tail Light	REAR PARK LIGHT NOT WORKING	الانارة

# O2 Body

الصبغ	BODY REPAINTED, PORTION REPAIRED MINOR DENTS	02.A Paint
Ç.	SCRATCHES	
غطاء المحرك	REFITTED	02.B Bonnet

غطاء المحرك REFITTED غطاء المحرك وجود مؤشر لحادث في المقدمة و PO2.C Sign of front accident

02.D Fenders FRONT FENDER REFITTED مدكار 02.E Pillars RIGHT SIDE OUTER PANEL PORTION REPAIRED &

REPAINTED

02.F Sign of back accident وجود مؤشر لحادث في الخلف 02.G Sign of side accident

#### 

حالة الجنوط	RIMS HAVE MINOR DENT SCRATCHES	03.A Rims Condition
الاطار الامامي	BOTH SIDE 2020 & WORN OUT	03.B Front Tyre
الاطار الخلفي	BOTH SIDE 2018/2019 CRACKED	03.C Rear Tyre

DEFECT	REMARKS	
04 Chassis Condition		الشاصي
04.A Chassis	FRONT LEFT SIDE END , REAR LEFT SIDE CHASSIS EXTENSION REPAIRED	الشاسيه
05 Suspension System		ممتص الصدمات
05.A Ball Joint	BOOT CUT	مفصل کروي
05.B Arms	LOWER ARM BUSHES CUT	ازرع
<b>06 Transmission Condition</b>		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة الجير النظرى
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Interior Condition		الحاله الداخليه
08.A AC Condition	FRONT RIGHT SIDE GRILL LOW COOLING	المكيف
08.B Dash Board	PORTION LOOSE	لوحة القياده
08.C Door Panel	LEFT SIDE PORTION LOOSE	لوحة بطانة الباب
09 Seats Condition		المقاعد
09.A Seat Condition	FRONT SEATS SIDE COVER LOOSE & LEFT SIDE SEAT ADJUSTMENT HANDLE DAMAGED	حالة المقاعد
10 Engine Condition		المحرك
10.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**









Plate Details: V 55621 Dubai Private Chassis No: 1ZVBP8AN6A5163248 Vehicle Make : FORD Vehicle Model: MUSTANG Vehicle Class: Light Vehicle Body Type: Coupe Fuel: Benzene Color: Red, White **Drive Direction:** Left Hand Side Dimensions : (H x W x L) --x--x--Current Odometer: 176936 Kms. Origin: **United States** Model Year: 2010 Gear Type: Automatic Engine Size: 3600 CC Engine No: NIL Horse Axles No: Power: Cylinders: No Of 6 Doors: No Of Seats: 4 G. V. W. : 2150 Kgs. Empty 1200 Kas. Weight:

111		

### ARetest can be done only in Dubai

Certificate Number : Inspection Date : Certificate Print Date :		5-TAS-2022-17365774			
		08-08-2022 08-08-2022			
Vehicle 1	Testing Partner:	Tasjeel			
Vehicle Testing Center: Total Time Taken:		Tasjeel Al Aweer 10 min 37 sec			
					Appointr Number
Start	15:11	End Time: 15:21			
Time :		Token No.: 195			
Lane :	02	Prints No: 1			
Attempt	: 1				

#### Parameter Readings

Vehicle on Petrol HC

Service	brake	imbalance	ог
front ax	le		

4 %

Reading 4256 PPM VOL Service brake imbalance on rear axle 23 %

Parking brake imbalance between LHS and RHS 8 % Vehicle on Petrol CO Reading 2.45 %

# Inspection Findings

Defects	Issue Severity		,
Front and Rear Windshields remove rear fins from windshield	Obstructed	Major	
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major	
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major	A
Engine	Misfiring	Major	
Discrepancies	Old Value Ne	w Value	Verified

Discrepancies	Old Value	New Value	Verified
Paint Change Color	Red , White	Red , Black	
THE PROPERTY OF THE PROPERTY O		,	

#### Inspection Remarks:

FRONT BOTH SIDE BULK HEAD, BUMPER FRAME, RADIATOR. SUPPORT FRAME & RIGHT SIDE FENDER FRAME, FENDER APRON, REAR LEFT SIDE CHASSIS REPAIRED. RIGHT SIDE CHASSIS MINOR DENT & END REPAIRED. OLD

#### Payment Details

Inspection Performed by 35063 Cash 17365774 AED 170 Collected on 08/08/2022

Parking Slot No Service Name Attempt Received by

-- Registration Test 1 Sittu Paloth Sreesan Paloth

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.