

Queue Number 2784395

Transaction Date 24 Sep 2026, 11:01:08

Site Name
840 - Emirates AuctionsTransaction Number
23065629 (CC10006) (CC10006)

Vehicle Details

Chassis Number	5NPEC4AC7B*****
Specification	Imported
Make	Hyundai
Model	Sonata
Model Year	2011
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	MINOR DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED ON BODY	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY , RUSTY	الارضية
01.D Bumper	MISALIGN PORTION CRACK	دعامية
01.E Trunk	NOT OPEN	صندوق
01.F Fuel Tank	DENT, GETTING RUSTY	خزان الوقود

02 Chassis Condition الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS RUSTY, BULGE, HOLE	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Mount	BUSHES CUT	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY KEY MISSING	الحالة النظرية للمحرك

04 Seats Condition المقاعد

04.A Seat Condition	PORTION WORN OUT CRACKED	حالة المقاعد
---------------------	--------------------------	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED, DAMAGED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED,	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	RUSTY, HOLE ,WEAK	ممتص الصدمات ازرع مفصل كروي
08.B Shock Absorber	RUSTY	
08.C Arms	BUSHES CUT	
08.D Ball Joint	BOOT CUT	
09 Steering Condition		المقود
09.A Steering Boot	BOOT CUT	ربلة المقود
09.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED / CENTER CONSOLE BOX WORN OUT	اخرى
10.B Mirror	RIGHT SIDE VIEW MIRROR COVER CRACKED	المرآيا
10.C AC Condition	NOT CHECKED	المكيف
10.D Dash Board	GETTING FADED PORTION WORN OUT CRACKED	لوحة القيادة
10.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae